City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Mar 12, 2024 Inspection Result: FAILED

Permit Number: E-21-0313

Property Address: 1015 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: DP EXCAVATION 11410 316th st e GRAHAM, WA 98338 (253) 720-

7790DP EXCAVATION 11410 316th st e GRAHAM, WA 98338 (253)

720-7790

To construct: PARKING LOT EXPANSION W. 675 STALLS, CFG~SHB-TC PARKING

EXPANSION/BENAROYA

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: Multiple bio-swales are rilling.

Heavy silt is entering the clean storm system by way of multiple finished bio-swales.

Second parking area has silt running down the asphalt due to upper parking lot not being stabilized. Note: HIGHLY recommend getting the design engineer involved. This issue is occurring with minimal runoff. What will happen when the entire upper lot is paved? The steep design of the bio-swales is and will always be an issue unless bottom can be stabilized ASAP. (sod lined) See corrections below!

Corrections:

- 1 Clean swale between upper and lower parking lot.
 - Stop rilling in finished bio-swales. Establish bio-swale bottoms.
 - Keep BMP's in place to protect inlets.
 - Maintain CESCL inspections and SWPPP on site!!!


Sincerely,



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org



Jason Little Engineering Tech IV JLittle@PuyallupWA.gov (253) 435-3636