



City of Puyallup

**Engineering Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

## INSPECTION REPORT

**Date of Inspection:** Jun 07, 2024

**Inspection Result:** **PARTIAL PASS**

**Permit Number:** PRFUP20231536

**Property Address:** 1006 39TH AVE SE, PUYALLUP, WA 98374;

**Contractor:** PSE - INFRASOURCE 3130 S 38TH ST TACOMA, WA 98409

**To construct:** 109145875 - Gas Main remediation - Install 1598' of 2" gas main, we will replace 8 services and install 7 test sites (T&T). Sidewalk was considered but not enough room for our gas utilities to be safely installed requesting hard surface cuts - detailed in restoration plan. Work is primarily on 10th St SE.

On this day we have inspected your construction for **Engineering Daily Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** All asphalt and concrete restoration has been laid out.  
See corrections.

**Corrections:**

- 1 - Where gas services went under curb and gutter a hoe pack or jumpin jack (not plate compactor) will need to be used on both sides prior to pave and concrete.
  - Intersection of 10th and 39th. Patches will need to be placed a day before grind and overlay. No patching and grind and overlay in the same night. Patches need to be fully cooled prior to grind and overlay.
  - Please schedule restoration inspection for the day of saw cutting. Saw cutter will be sent away if this is not done.
  - On the thin asphalt areas, NO overcut.
  - Landscape will be inspected towards end of asphalt and concrete restoration.
  - Entire street (10th) will need to be swept gutter to gutter.

Sincerely,



City of Puyallup

---

**Engineering Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

Jason Little  
Engineering Tech IV  
JLittle@PuyallupWA.gov  
(253) 435-3636