

Seattle Tacoma Portland	1011 Western Avenue, Suite 810   Seattle, WA 98104   206.292.5076 1250 Pacific Ävenue, Suite 701   Tacoma, WA 98402   253.383.2797 101 SW Main Street, Suite 1602   Portland, OR 97204   503.232.3746			
	www.pcs	-structural.com		
	April 22, 2025		Calculations required to be provided by the Permittee on site for all Inspections	City of Puyallup Building REVIEWED FOR
		iyashi 5th St #200 WA 98103 Ellen Hagen	PRRF20250705	FOR COMPLIANCE SKinnear 06/24/2025 10:51:56 AM
	RE:	Community Health Ca	are Puyallup – Silo Roof	PART OF WASHINGTON

## Dear Ellen:

We have reviewed your summary of replacement roof loading on the existing Silo Roof at the 201 W. Main property. Per your description, the summary of the new roof profile and its corresponding weights are as follows:

## From Existing Roof Layer (to remain) outward:

Limited sheet metal patching to cover holes in existing metal roofing, flat stock sheet metal thickness would match existing. (no added weight) Rigid Insulation infill to depth of standing seam. Estimated Weight = 2" thick is 0.38 PSF (to be verified – unknown what standing seem height is but assuming based off photos) 1/4 inch USG Securock Brand Ultralight Glass-Mat Roof board = 1.2 PSF Roofing Membrane Layer = .23 PSF

Total added weight = 1.81 PSF

We were also on site to review the silo on March 5, 2025. The structure of the silo is plate steel and appeared to be in good condition. Shape, size, and material appeared to match the existing drawings provided. We observed no signs of structural distress or deterioration.

The existing silo should be able to adequately support this new re-roof profile.

Thank you for the opportunity to be of continued service to Miller Hayashi and Community Health. Please contact us if you have any questions.

Very truly yours,

PCS STRUCTURAL SOLUTIONS

Todd Parke, S.E President | Managing Principal

TPPjcl 22-537



22537 ltr 2025-04-09 tpp R2