



Response to Correction Letter for Permit Application #PRFA20251172.

1. Plans have been adjusted to separate above ceiling detectors and reflected ceiling plan. Please see sheet FA-06.
2. The following notice has been provided to the general contractor:

Notice to General Contractor: Detector Sensitivity Testing Prior to Commissioning

Please be advised that a **detector sensitivity test** will be conducted prior to system commissioning. Any detectors found to be **dirty or otherwise compromised** during this testing will require **replacement at the General Contractor's expense**.

This measure ensures compliance with system performance standards and guarantees proper functionality upon commissioning.

3. Detectors have been added and relocated to meet spacing requirements.
4. Detectors have been added to cover vestibules please see clouded areas on sheet FA-04 and FA-05.
5. A detector has been installed to account for accordion door. See clouded area on sheet FA-05
6. Detectors have been added and relocated to meet spacing requirements.
7. Monitor modules have been added to monitor generator run and generator fault.
8. Battery calcs have been updated please see clouded area on FA-01.
9. Plans have been revised to comply with total coverage Per NFPA 72.

Neville Hylton
Install Manager
NICET IV FAS 126511