


Post and provide Puget Sound Clean Air Agency notification in accordance with agency rules and requirements.



30620 Pacific Hwy S, #103,  
Federal Way, WA 98003  
(253) 941-4343



PRDE20241092

Enclosed please find the analytical report for one or more samples submitted for analysis by Polarized Light Microscopy.

**The six types of asbestos fibers are chrysotile, amosite, crocidolite, tremolite, anthophyllite and actinolite. A sample which contains more than 1% asbestos is considered positive and is defined by the EPA as an Asbestos Containing Material (ACM).**

The samples were analyzed in accordance with EPA method 600/R-93/116 and 600/M4-82-020 which has a detection limit of approximately 1%. The analyst used a stereomicroscope to visually inspect the sample to determine homogeneity and material descriptions. The sample was then viewed under a polarized light microscope to determine the presence and percentage of asbestos and non-asbestos fibers.

After analysis is complete, all paperwork is filed together, and kept in a secure locked filing cabinet. Asbestos Northwest ensures that the files will not be tampered with at any time and will only be removed if the client requests reanalysis or a modification to the report. If you have any concerns or comments, contact us at [feedback@asbestosnw.com](mailto:feedback@asbestosnw.com) or fill out our survey at [asbestosnw.com/survey](http://asbestosnw.com/survey)

Thank you,

-These results are only applicable to the **samples enclosed** with information provided by the client. This report may not be reproduced, except in full, without the approval of the laboratory. This report may not be used to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government.-

### Bulk Sample Log / Chain of Custody

Client Company: Tacoma Abatement Company, LLC  
 Client Address: 5111 S Burlington Way  
Tacoma, WA 98409  
 Phone #: (253) 830-5945  
 Fax #: (253) 276-0267

LAB: ANW  
 LAB Job #: 202411956  
 # of Samples: 14

Job Name: CCS 819 Project  
 Job Address: 819 21<sup>st</sup> St SE  
Puyallup, WA 98372

Report Results To: Matthew Wise  
 At Phone #: 253-885-0165  
 Fax Results: (253) 276-0267  
 Mail Hard Copy: 5111 S Burlington Way  
Tacoma, WA 98409  
 Email Copy To: matt@tacomaabatementcompany.com

Type of Analysis (Check One)

- |                                     |            |                          |                   |
|-------------------------------------|------------|--------------------------|-------------------|
| <input type="checkbox"/>            | ASBESTOS   | <input type="checkbox"/> | LEAD              |
| <input type="checkbox"/>            | PCM (air)  | <input type="checkbox"/> | Paint             |
| <input checked="" type="checkbox"/> | PLM (bulk) | <input type="checkbox"/> | Soil              |
|                                     |            | <input type="checkbox"/> | Dust/Wipe (area?) |
|                                     |            | <input type="checkbox"/> | Air (volume?)     |
|                                     |            | <input type="checkbox"/> | TCLP              |

REGULAR  RUSH 3 day

Condition of Package:  Good  Damaged (No Spillage)  Severe Damage (Spillage)


Lab ID	Sample ID	Type	Location
1		JC/TX	Living Room H211
2		TX	Hall
3		TX	Back Entry
4		JC/TX	M Bedroom
5		TX	"
6		TX	"
7		JC/TV	Back Bath
8		TX	"
9		TX	"
10		S.VI	Hall Bath
11		File	Pantry
12		T/M	Back Entry
13		File	Back Bath
14		3-Tab	Roof

	Signature	Date	Time
Sampled By:	<u>Ray W</u>	<u>5/13/24</u>	
Delivered By:	<u>Ray W</u>	<u>5/13/24</u>	
Received By:	<u>Crystal Andrzejewicz</u>	<u>5/13/24</u>	<u>11:05 AM</u>
Analyzed By:	<u>Cathy Butler</u>	<u>5-15-24</u>	
Special:	Read Abatement Sample # _____ ONLY if Sample # _____ is Greater Than .01 f/cc.		

Falsified



Asbestos Northwest, LLC  
 30620 Pacific Hwy S, #103, Federal Way, WA 98003  
 Ph: (253) 941-4343



**Batch Number: 202411956**

**PLM Analysis by EPA Method 600/M4-82-020 and 600/R-93/116**

This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government.

**Attn: Matt Ware**  
**Tacoma Abatement Company**  
**5111 S Burlington Way Tacoma WA 98409**

**Date Received: 5/13/2024**  
**Date Analyzed: 5/15/2024**  
**Samples Received: 14**  
**Samples Analyzed: 14**


**Project: CCS 819 Project**  
**Location: 819 21st St. SE Puyallup, WA 98372**

Client Sample ID	Lab Sample ID	Layer	Description	Matrix	% Non-Asbestos Fibers	% Asbestos Fibers and Type
1		1	White powdery material with paint	Binder/filler, Paint	2% Cellulose	<b>None Detected</b>
		2	White chalky material with paint and paper	Filler/binder, Gypsum, Paint	25% Cellulose, Glass fibers	<b>None Detected</b>
2		1	White powdery material with paint	Binder/filler, Paint	2% Cellulose	<b>None Detected</b>
		2	Paint	Paint	None Detected	<b>None Detected</b>
3		1	White powdery material with paint	Binder/filler, Paint	2% Cellulose	<b>None Detected</b>
		2	White chalky material with paper	Filler/binder, Gypsum	25% Cellulose, Glass fibers	<b>None Detected</b>
4		1	White powdery material with paint	Binder/filler, Paint	2% Cellulose	<b>None Detected</b>
5		1	White powdery material with paint	Binder/filler, Paint	2% Cellulose	<b>None Detected</b>

Analyzed by: Cathy Butler *Cathy Butler*



Asbestos Northwest, LLC  
 30620 Pacific Hwy S, #103, Federal Way, WA 98003  
 Ph: (253) 941-4343



**Batch Number: 202411956**

**PLM Analysis by EPA Method 600/M4-82-020 and 600/R-93/116**

This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government.

**Attn: Matt Ware**  
**Tacoma Abatement Company**  
**5111 S Burlington Way Tacoma WA 98409**

**Date Received: 5/13/2024**  
**Date Analyzed: 5/15/2024**  
**Samples Received: 14**  
**Samples Analyzed: 14**


**Project: CCS 819 Project**  
**Location: 819 21st St. SE Puyallup, WA 98372**

Client Sample ID	Lab Sample ID	Layer	Description	Matrix	% Non-Asbestos Fibers	% Asbestos Fibers and Type
		2	White chalky material with paint and paper	Filler/binder, Gypsum, Paint	25% Cellulose, Glass fibers	<b>None Detected</b>
6		1	White powdery material with paint	Binder/filler, Paint	2% Cellulose	<b>None Detected</b>
		1	White chalky material with paint and paper	Filler/binder, Gypsum, Paint	25% Cellulose, Glass fibers	<b>None Detected</b>
7		1	White powdery material with paint	Binder/filler, Paint	2% Cellulose	<b>None Detected</b>
		2	White chalky material with paper	Filler/binder, Gypsum	25% Cellulose, Glass fibers	<b>None Detected</b>
8		1	White powdery material with paint	Binder/filler, Paint	2% Cellulose	<b>None Detected</b>
		2	White chalky material with paper	Filler/binder, Gypsum	25% Cellulose, Glass fibers	<b>None Detected</b>

Analyzed by: Cathy Butler *Cathy Butler*



Asbestos Northwest, LLC  
 30620 Pacific Hwy S, #103, Federal Way, WA 98003  
 Ph: (253) 941-4343



**Batch Number: 202411956**

**PLM Analysis by EPA Method 600/M4-82-020 and 600/R-93/116**

This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government.

**Attn: Matt Ware**  
**Tacoma Abatement Company**  
**5111 S Burlington Way Tacoma WA 98409**

**Date Received: 5/13/2024**  
**Date Analyzed: 5/15/2024**  
**Samples Received: 14**  
**Samples Analyzed: 14**

**Project: CCS 819 Project**  
**Location: 819 21st St. SE Puyallup, WA 98372**

Client Sample ID	Lab Sample ID	Layer	Description	Matrix	% Non-Asbestos Fibers	% Asbestos Fibers and Type
9		1	White powdery material with paint	Binder/filler, Paint	2% Cellulose	None Detected
		2	White chalky material with paper	Filler/binder, Gypsum	25% Cellulose, Glass fibers	None Detected
10		1	Tan sheet vinyl	Vinyl/binder	None Detected	None Detected
		2	Yellow mastic	Mastic/binder	None Detected	None Detected
11		1	Tan sheet vinyl	Vinyl/binder	None Detected	None Detected
12		1	Gray tile	Vinyl/binder, Mineral grains	1% Cellulose	None Detected
		2	Yellow mastic	Mastic/binder	1% Cellulose	None Detected
13		1	Tan sheet vinyl	Vinyl/binder	None Detected	None Detected
14		1	Black asphaltic material with sand	Asphalt/binder, Sand	50% Cellulose, Glass fibers,	None Detected

Analyzed by: Cathy Butler *Cathy Butler*