

TANK PUMPING REPORT

PRSC20260387

Site Name:

Location: 302 TODD RD NE
 Puyallup
 Tax ID: 0420222028
 Use:

Service Company:

Drain-Pro, Inc.
 PO Box 100
 Puyallup, WA 98372
 253-926-5586

Serviced: 03/26/2026 by: Brandon Lewis

Submitted 03/30/2026 by: Dana Malarcher

Dump Location: King County Metro Wastewater Treatment Plant

Jurisdiction ID: ON2026-00142

COMMENTS

Pump for Demo.

| TANK: Septic Tank - 1 Compartment | | |
|---|----------|--|
| Tank Pumped: | YES | |
| Total Gallons pumped from tank (Number only, no text): | 750 | |
| Tank Size (Gallons)(Number only, no text): | 750 | |
| Tank depth below grade (inches): | 0 | |
| Effluent level within operational limits (if NO explain in comments): | YES | |
| Effluent returning back into tank after pumping: | NO | |
| Access Risers installed to grade (N/A if not present): | N/A | |
| Tank Construction Material: | Concrete | |
| Tank Condition Good: | YES | |
| Baffles in good condition (N/A if not present): | YES | |
| Effluent screen cleaned (N/A if not present): | N/A | |
| Effluent surfacing around site components (N/A if not checked): | NO | |
| Tank abandoned after pumping: | YES | |
| Were repairs made to the Tank or Tank Components? (if YES explain in comments): | NO | |
| Compartment 1 Scum accumulation (Inches, if other specify): | 0 | |
| Compartment 1 Sludge accumulation (Inches, if other specify): | 12 | |

| TANK: Septic Tank - 1 Compartment | | |
|---|----------|--|
| Tank Pumped: | YES | |
| Total Gallons pumped from tank (Number only, no text): | 750 | |
| Tank Size (Gallons)(Number only, no text): | 750 | |
| Tank depth below grade (inches): | 0 | |
| Effluent level within operational limits (if NO explain in comments): | YES | |
| Effluent returning back into tank after pumping: | NO | |
| Access Risers installed to grade (N/A if not present): | N/A | |
| Tank Construction Material: | Concrete | |
| Tank Condition Good: | YES | |
| Baffles in good condition (N/A if not present): | YES | |
| Effluent screen cleaned (N/A if not present): | N/A | |
| Effluent surfacing around site components (N/A if not checked): | NO | |
| Tank abandoned after pumping: | YES | |
| Were repairs made to the Tank or Tank Components? (if YES explain in comments): | NO | |
| Compartment 1 Scum accumulation (Inches, if other specify): | 0 | |
| Compartment 1 Sludge accumulation (Inches, if other specify): | 10 | |

This report indicates certain characteristics of the onsite sewage system at the time of visit. In no way is this report a guarantee of operation or future performance.