

September 10, 2021

David Drake
Fire Inspector
City of Puyallup
333 S Meridian, 2nd Floor
Puyallup, WA 98731

**Re: *Fire Construction Permit Application
CUP Modification
Reuse of Storage Tank 3 for Used Oil***

Dear Mr. Drake;

Ecolube Recovery has petitioned for a minor modification under Conditional Use Permit No. P-18-0154 to allow for the repurposing of Tank 3 at the Ecolube Recovery terminal. Tank 3 will be used in Used Motor Oil storage in an identical fashion as Tanks 1, 2 & 4. The modification is being requested to allow for segregation of oil to differentiate blends according to product specifications and reduce overall transportation. ChemE Consulting (ChemE) is pleased to present this information on behalf of Ecolube Recovery in support of the Application for Fire Code - Construction Permit for repurposing Tank 3 for liquid storage and transfer operations located at 213 10th Street SE; Puyallup, WA 98731.

Summary of Work

The proposed modification will add Tank 3 to the existing tanks located at the proposed site. Tank 3 was evaluated by a third party tank inspection firm Mistras to evaluate the condition of the tanks and found to be in satisfactory condition pending correction of mandatory recommendations.

Tank 3 anchoring design was further evaluated by a structural engineer (Conlee Engineers) to verify the anchoring is consistent with the building code at the time of installation. The structural engineer's report shows that the anchoring was consistent with building code with the addition of one missing 1-1/4" anchor bolt with 1-1/4" HIT-RE-500V3 with 13" embedment.

Tank inspection report for Tank 3 and structural engineer's calculations are attached at the end of this letter.

Detailed Scope of Work for Tank 3

The following scope of work is intended for the development for Tank 3.

1. Tank Inspection and Mechanical Upgrades & Maintenance per Mistras Report

- Install new 10” Emergency vent assembly on top of tank
- Replace existing 3” conservation vent with 3” gooseneck pipe vent
- Install one missing anchor bolt per recommendation (Hilti 1-1/4” HIT-RE-500V3) with Special Inspection
- Install level transmitter on existing 3” flange nozzle per dwg. P-101.
- Install Float High Level Switch (LSHH) on existing 3” flange nozzle per dwg. P-101.
- Change out all flange gaskets
- Hydraulic fill test to verify that tank is liquid tight
- Install 3” pipe from unloading manifold pipe to top of Tank 3
- Install 4” pipe from Tank 3 to loading manifold pipe
- Repair coating wear on caged ladder rungs

(Note: Internal lining referenced in Mistras Inspection report is NOT required for Used Oil Service.)

2. Electrical

- Install level monitoring, controls and interlocks for overflow protection

Reference Documentation

The scope of work is supported by the following documentation located in attached appendices.

App 1: Tank Inspection

App 2: Tank Foundation Evaluations

App 3: Drawings

If you have any questions or comments with the permit application documentation, please contact me at 360-355-5513.

Sincerely,



David R. Ravander, P.E.

Principal Engineer



ChemE Consulting, LLC

9021 Willow Grove Rd

Longview, WA 98632

David@Chemeconsulting.com / 360-355-5513

Appendix 1

Tank Inspection Report – Mistras

STEEL TANK INSTITUTE
AST Certification Report
Per STI SP001, 6th Edition, January 2018

Ecolube LLC
Tank No. 3
Out of Service Inspection
Located at: Puyallup, WA

Inspected on: 6-26-2019

Report No. 40677049-1

Prepared By:
 **MISTRAS** | Services
A World of NDT Solutions | Division
7820 South 210th Street, Suite 110
Kent, WA 90032
(206) 764-8123



Table of Contents

- 1.0 Job Information
- 2.0 Tank Inspection Data Sheet
- 3.0 Suitability for Service
- 4.0 Summarized Recommendations
- 5.0 Remaining Life Calculations
 - 5.1 Shell Plates Remaining Life
 - 5.2 Floor Plate Remaining Life
- 6.0 Ultrasonic Thickness Data
 - 6.1 Shell Plate UT
 - 6.2 Floor Plate UT
 - 6.3 Shell Nozzle UT
 - 6.4 Fixed Roof Nozzle UT
- 7.0 STI SP001 Checklists
- 8.0 Photographs
- 9.0 NDE Equipment Used
- 10.0 Inspector Certifications
- 11.0 Drawings



1.0 Job Information

Job Location :

EcoLube LLC
213 10th St SE
Puyallup, WA
98372 USA

Customer Representative :

Eric Spencer

Customer Phone Number :

1-503-893-1933

Job Charge Number :

921793-2019-06-21

Report Number :

40677049-1

Mistras Work Order Number :

T61180-40677049

Inspection Personnel Provided :

Zach Libby
API 653 Certified Inspector
API 653 (46293)/API 510 (42713)/API 570 (41560)/UTT
Brandon Gonzalez
Level II Technician
UTT/PT/MFL



2.0 Tank Inspection Data Sheet

General :

Tank Number	3
Owner	EcoLube LLC
Design Standard	Unknown
Tank Location	Puyallup, WA
Product	Deicer
Specific Gravity	1.28
Manufacturer	Unknown
Manufacture Date	1988
Cathodic Protection	No
Data Plate Present	No
Data Plate Condition	N/A

Dimensions :

Diameter (ft)	11.0
Height (ft)	36.0
Capacity Nominal (bbls)	609.34

Geometry :

Foundation	Raised Concrete Pad
Bottom	Butt Welded Double Bottom
Shell	Full Lap Welded
Roof	Self-Supporting Cone

Access :

Top	From Cage Ladder
Internal	Shell Manway

Coatings :

Shell	Insulated
Roof	Insulated
Bottom	Internal Thin Film Epoxy



3.0 Suitability for Service

The Ecolube tank 3 was inspected and tested in accordance with all applicable requirements of STI SP001 January 2018 6th Edition.

Per STI SP001 the tank is classified as a Category 1 and should be inspected monthly and annually by the owner's inspector as required by Section 6.0 of STI SP001. Formal External Inspections shall be performed as required by the owner's future SPCC plan and established schedule. This tank is considered suitable for service provided that all venting and level monitoring equipment is reinstalled and that any mandatory recommendations are completed before commissioning the tank.

Inspectors Signature: _____

STI SP001 Certification No. AC 44164



4.0 Summarized Recommendations

Based on the inspection completed this tank is a Category 1 in accordance with STI SP001, 6th Edition. The following section summarizes the recommendations which are based on the findings in the preceding checklists.

Note: Recommendations in bold underline are to be considered mandatory recommendations. Those NOT in bold underline are to be considered optional repairs/recommendations to be performed at the discretion of the client.

Foundation and Containment

- 1) There are some minor cracks in the containment area walls and floor. The client should consider sealing these cracks in the future to prevent further degradation.
- 2) The containment floor joints are not sealed and have small scattered areas of foliage growth. The client should seal this joint to prevent water damage and foliage growth in the future.
- 3) There are large areas of foliage growing around the base of the tank. The client should consider removal at the next opportunity. Foliage can continue to expand and trap moisture against the tank.
- 4) The tank rests on a 6" raised concrete pad. The viewable areas contained some moderate spalling and erosion. The customer should repair these areas in the future to mitigate further degradation.
- 5) This tank contains seismic anchoring details. Inspection noted that there is currently 1 missing long bolt out of a total of 8. Due to the tank's dimensions, it is likely that all bolts are required. The customer should replace the missing bolt before recommissioning the tank.

Bottom

- 6) The dead space between the double floor has 3 visible 3" x 3" cutouts in the shell. The space appears to have been filled with a type of spray foam in effort to seal the area from any potential bottom leaks. This configuration is not ideal for typical leak detection. These cutouts should be closed up by welded inserts. The customer should also install a threaded coupling with a bull plug in the lower region of the space so that periodic leak monitoring can be performed. Note: There are likely more of these cutouts behind the insulation sheeting which aren't readily visible.
- 7) The primary bottom is sloped to the east and consists of 2 butt welded plate. Inspection noted that an area 6" to 12" west of the weld was bulged approximately 1" to 2", across the entire diameter of the tank floor. The client should prep the weld by needle gunning or power buffing and perform magnetic particle testing on the weld to determine if any stress cracking has occurred.
- 8) There is currently no visible grounding component installed. The customer should install a new electrical ground near the base of the tank to allow static discharge and to protect against lightning.
- 9) There are areas of heavy internal coating degradation present with scale buildup and non-measurable corrosion forming. The client should prep and recoat the affected area at the next opportunity. **Note: If an internal liner is required for the new intended service, this recommendation would be mandatory.**



- 10) There are 2, 1.5" diameter stainless steel tube banks installed which were used for heating purposes. Visual inspection noted that many of the U-bolts which secure the piping to the supports, were broken or missing. If this component is to be used again in future service, all faulty hardware should be replaced.

Shell

- 11) There were many suspect CUI (corrosion under insulation) areas throughout the exterior of the shell due to various openings and damage within the jacketing. Internal UT testing was performed on the shell interior of course 1 and 2 confirming that external metal loss up 0.06" has occurred in some locations. The external shell was also visible through UT ports that were installed during this inspection, and there appears to be a heavily degraded coating present in the upper courses of the tank. If the tank is to be re-used, the client should highly consider stripping sample areas of insulation at strategic locations to better evaluate the exterior condition of the tank shell.
- 12) There are areas of heavy internal coating degradation present with scale buildup and non-measurable corrosion forming. The client should prep and recoat the affected area at the next opportunity. **Note: If an internal liner is required for the new intended service, this recommendation would be mandatory.**

Shell Nozzles and Appurtenances

- 13) **The nozzle and manway gaskets appear to be original and show evidence of deterioration. The customer should change out all existing gaskets and ensure compatibility with the newly intended service.**
- 14) There internal nozzle bores, couplings and manway neck and areas of heavy internal coating degradation present with scale buildup and non-measurable corrosion forming. The client should prep and recoat the affected area at the next opportunity. **Note: If an internal liner is required for the new intended service, this recommendation would be mandatory.**
- 15) There is no data plate installed on the tank. The customer should locate historical records and purchase a new plate to be installed in conspicuous location.

Fixed Roof

- 16) The roof exterior has been sealed in a spray foam insulation. Ports were installed for UT testing and visible, black scale corrosion was noted which indicates the likelihood of CUI occurring. The customer should remove the foam insulation to better evaluate the exterior condition of the tank roof.
- 17) **There is currently a 3" atmospheric vent installed and what is assumed to be a 20" emergency vent that has been enclosed by spray foam insulation. If the tank is to be used again, these vents should be serviced and the 20" vent made operational. Note that per STI SP001, for normal venting the minimum size required is 3" and for emergency venting the minimum size required is 10", so the existing vents meet the size requirements.**

Access Structures

- 18) The cage ladder rungs had notable coating wear and failure throughout. The client should clean and recoat the affected areas in the future.

Inspectors Signature: _____

STI SP001 Certification No. AC 44164



5.0 Remaining Life Calculations

The following details the calculated corrosion rates and remaining life based on the findings from this inspection. The following items have been calculated:

$$C_r = \frac{t_{previous} - t_{actual}}{\text{Years between } t_{previous} \text{ and } t_{actual}} \text{ in inches per year}$$

$$R_L = \frac{t_{actual} - t_{min}}{C_r} \text{ in years}$$

- C_r = Corrosion Rate in inches per years
- R_L = The Remaining Life of a tank component in years.
- $t_{previous}$ = Thickness at the same location as t_{actual} measured during a previous inspection or nominal thickness, in inches.
- t_{actual} = The thickness measured at the time of inspection for a given location or component used to determine the minimum allowable thickness, in inches.
- t_{min} = The minimum allowable thickness for a given location or component, in inches.

5.1 Shell Plates Remaining Life

Reference: API 653, 4th Edition, Add. 1, Aug. 2010, Paragraph 4.3.3.1

Course	$t_{previous}$ Previous Thickness (in)	Year Obtained	t_{actual} Actual Thickness (in)	Year Obtained	C_r Corrosion Rate (in/yr.)	t_{min} Minimum Allowable Thickness (in)	R_L Remaining Life (yr.)
6	0.188	1988	0.180	26-Jun-19	0.00026	0.100	305.65
5	0.188	1988	0.180	26-Jun-19	0.00026	0.100	305.65
4	0.188	1988	0.184	26-Jun-19	0.00013	0.100	641.87
3	0.188	1988	0.184	26-Jun-19	0.00013	0.100	641.87
2	0.188	1988	0.126	26-Jun-19	0.00203	0.100	12.82
1	0.250	1988	0.201	26-Jun-19	0.00160	0.100	63.00



5.2 Floor Plate Remaining Life

t_{previous} Previous Thickness (in)	Year Obtained	t_{actual} Actual Thickness (in)	Year Obtained	C_r Corrosion Rate (in/yr.)	t_{min} Minimum Allowable Thickness (in)	R_L Remaining Life (yr.)
0.250	1988	0.233	26-Jun-19	0.00056	0.100	239.13



6.1 Shell Plate UT

The following table details all readings (in) from the shell UT survey. All scan drops were equally spaced at 8.635 ft.


Data and Statistics		1	2	3	4	Readings Line Average
Course 6	4	-	-	-	-	
	3	-	-	-	-	
	2	-	-	-	-	
	1	0.180	-	-	-	0.180
Course 5	4	-	-	-	-	
	3	-	-	-	-	
	2	-	-	-	-	
	1	0.180	-	-	-	0.180
Course 4	4	-	-	-	-	
	3	-	-	-	-	
	2	-	-	-	-	
	1	0.184	-	-	-	0.184
Course 3	4	-	-	-	-	
	3	-	-	-	-	
	2	-	-	-	-	
	1	0.184	-	-	-	0.184
Course 2	4	0.160	0.163	0.165	0.126	0.154
	3	0.170	0.149	0.163	0.168	0.163
	2	0.167	0.157	0.155	0.165	0.161
	1	0.170	0.165	0.174	0.170	0.170
Course 1	4	0.246	0.213	0.242	0.241	0.236
	3	0.242	0.222	0.241	0.222	0.232
	2	0.205	0.215	0.216	0.201	0.209
	1	0.239	0.220	0.222	0.240	0.230
Scan Line Average		0.194	0.188	0.197	0.192	0.193



The tables below present the statistics of the thickness readings (in) obtained on the Shell plates.

Course #	Min	Avg	Max
6	0.180	0.180	0.180
5	0.180	0.180	0.180
4	0.184	0.184	0.184
3	0.184	0.184	0.184
2	0.126	0.162	0.174
1	0.201	0.227	0.246
<i>Global</i>	0.126	0.193	0.246

The following chart depicts the average thickness reading (in) on the shell plates versus the course number.





6.2 Floor Plate UT

The following table details all readings (in) obtained on the floor plates. Typically, one reading was obtained in the corner of each plate and one in the center. Readings were taken from center in the 4 cardinal directions. There are 2 total plates installed.

Plate ID \ Reading ID	1	2	3	4	5	Avg
1	0.234	0.234	0.233	0.233	0.235	0.234
2	0.239	0.241	0.240	0.241	0.238	0.240
3	0.236	0.237	0.236	0.235	0.235	0.236
4	0.242	0.238	0.239	0.242	0.238	0.240
Avg	0.238	0.238	0.237	0.238	0.237	0.237

The table below presents the statistics of the thickness readings obtained on the floor plates.

UT Summary	
Maximum	0.242
Average	0.237
Minimum	0.233

6.3 Shell Nozzle UT

Item	Type	Service	Pipe Size (in)	Top (in)	Bottom (in)	Right (in)	Left (in)	Repad Thickness (in)	Flange Thickness (in)	Cover Thickness (in)	Comments
A	Manway	Internal Access	24	0.279	0.257	0.259	0.258	N/A	0.253	0.229	
B	Coupling	Open	1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Threaded
C	Coupling	Sensor	1	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Threaded
D	Nozzle	Suction	4	0.207		0.209	0.2	N/A	N/A	N/A	
E	Nozzle	Fill	4	0.226	0.227	0.227	N/A	N/A	0.806	N/A	
F	Cage Ladder	Roof Access	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
G	Nozzle	Blinded	8	0.252	0.242	0.253	0.243	N/A	1.112	N/A	
H	Nozzle	Open	1.5	0.145	0.14	0.135	0.15	N/A	0.777	N/A	
I	Nozzle	Steam	1.5	0.143	0.148	0.142	N/A	N/A	0.648	N/A	
J	Coupling	Sample	.75	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Threaded



6.4 Fixed Roof Nozzle UT

Item	Type	Service	Pipe Size (in)	North (in)	South (in)	East (in)	West (in)	Repad Thickness (in)	Repad Shape	Comments
AA	Nozzle	Blinded	3	N/A	N/A	N/A	N/A	N/A	N/A	All components obstructed by insulation.
AB	Pipe	Anchor	1.5	N/A	N/A	N/A	N/A	N/A	N/A	
AC	Pipe	Tape Guide	1.5	N/A	N/A	N/A	N/A	N/A	N/A	
AD	Pipe	Anchor	1.5	N/A	N/A	N/A	N/A	N/A	N/A	
AE	Nozzle	Blinded	3	N/A	N/A	N/A	N/A	N/A	N/A	
AF	Manway	Emergency Vent	20	N/A	N/A	N/A	N/A	N/A	N/A	
AG	Nozzle	Vent	3	N/A	N/A	N/A	N/A	N/A	N/A	



7.0 STI SP001 Checklists

STI SP001 AST RECORD

Owner Information	Facility Information	Installer Information
Name: EcoLube LLC	Name: *Same as owner	Name: Unknown
Number and Street: 213 10 th St SE	Number and Street:	Number and Street:
City, State, Zip Code: Puyallup, WA, 98372	City, State, Zip Code:	City, State, Zip Code:

Tank ID: 3		
Specification:		
Design:	<input type="checkbox"/> UL _____	<input type="checkbox"/> SWRI _____
	<input type="checkbox"/> Horizontal	<input checked="" type="checkbox"/> Vertical
	<input type="checkbox"/> Rectangular	
	<input type="checkbox"/> API _____	<input type="checkbox"/> Other
	<input checked="" type="checkbox"/> Unknown	
Manufacturer: Unknown	Contents: Deicer	
Construction Date: 1988	Last Repair/ Reconstruction Date: Unknown	
Dimensions: 11' D x 36' H	Capacity: 685.44 bbls	Last Change Of Service Date: Unknown
Construction:	<input type="checkbox"/> Bare Steel	
	<input type="checkbox"/> Cathodically Protected (Check one: A. <input type="checkbox"/> Galvanic or B. <input type="checkbox"/> Impressed Current) Date Installed:	
	<input checked="" type="checkbox"/> Coated Steel	<input type="checkbox"/> Concrete
	<input type="checkbox"/> Plastic/ Fiberglass	<input checked="" type="checkbox"/> Other
	<input checked="" type="checkbox"/> Double Bottom	<input type="checkbox"/> Double Wall
	<input checked="" type="checkbox"/> Lined Date Installed:	
Containment:	<input type="checkbox"/> Earthen Dike	<input type="checkbox"/> Steel Dike
	<input checked="" type="checkbox"/> Concrete	<input type="checkbox"/> Synthetic Liner
	<input checked="" type="checkbox"/> Other	
CRDM:	<input checked="" type="checkbox"/> Date Installed: 1988	Type: Raised Concrete Pad
Release Prevention Barrier:	<input checked="" type="checkbox"/> Date Installed: 1988	Type: Double Floor Design



STI SP001 MONTHLY INSPECTION CHECKLIST

General Inspection Information:

Inspection Date: 6-26-2019 Prior Inspection Date: Unknown Tank Inspected (ID #): 3	Retain Until Date: (36 months from inspection date) Inspector Name: Zach Libby
--	---

Inspection Guidance:

- For equipment not included in this standard, follow the manufacturer recommended inspection/testing schedules and procedures.
- The periodic AST inspection is intended for monitoring the external AST condition and its containment structure. This visual inspection does not require a certified inspector. It shall be performed by an owner's inspector who is familiar with the site and can identify changes and developing problems.
- Upon discovery of water in the primary tank, secondary containment area, interstice, or spill container, remove promptly or take other corrective action. Before discharge to the environment, inspect the liquid for regulated products or other contaminants and dispose of it properly.
- (*) designates an item in a non-conformance status. This indicates that action is required to address a problem.
- Non-conforming items **important to tank or containment integrity** require evaluation by an engineer experienced in AST design, a certified inspector, or a tank manufacturer who will determine the corrective action. Note the non-conformance and corresponding corrective action in the comment section.
- Retain the completed checklists for 36 months.
- In the event of severe weather (snow, ice, wind storms) or maintenance (such as painting) that could affect the operation of critical components (normal and emergency vents, valves), and inspection of these components is required immediately following the event.

Item	Task	Status	Comments
1.0 Tank Containment			
1.1 Containment Structure	Check for water, debris, cracks or fire hazard	<input checked="" type="checkbox"/> Yes* <input type="checkbox"/> No <input type="checkbox"/> N/A	Gaps at floor joints noted. Some minor cracks in walls and floor also observed.
1.2 Primary Tank	Check for water	<input type="checkbox"/> Yes* <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A	No water in primary tank.
1.3 Containment drain valves	Operable and in a closed position	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	None installed or located. Drain tiles present.
1.4 Pathways and entry	Clear and gates/doors operable	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No* <input type="checkbox"/> N/A	Access points acceptable.
2.0 Leak Detection			
2.1 Tank	Visible signs of leakage	<input type="checkbox"/> Yes* <input checked="" type="checkbox"/> No	No leak detection devices.
2.2 Secondary Containment	Visible signs of leakage from tank into secondary containment	<input type="checkbox"/> Yes* <input checked="" type="checkbox"/> No	No product leaks present.



2.3 Surrounding Soil	Visible signs of leakage	<input type="checkbox"/> Yes* <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A	No signs of leaks.
2.4 Interstice	Visible signs of leakage	<input type="checkbox"/> Yes* <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A	No way to confirm. No leak detection ports.

Item	Task	Status	Comments
3.0 Tank Equipment			
3.1 Valves	a. Check for leaks	<input type="checkbox"/> Yes* <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A	No leaks discovered.
	b. Tank drain valves must be kept locked.	<input type="checkbox"/> Yes* <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	
3.2 Spill containment boxes on fill pipe	a. Inspect for debris, residue and water in the box and remove	<input type="checkbox"/> Yes* <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	None.
	b. Drain valves must be operable and closed	<input type="checkbox"/> Yes* <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	
3.3 Liquid level equipment	a. Both visual and mechanical devices must be inspected for physical damage.	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	Equipment removed or offline at time of inspection.
	b. Check the device is easily readable	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	

Item	Task	Status	Comments
3.4 Overfill equipment	a. If equipped with a "test" button, activate the audible horn or light to confirm operation. This could be battery powered. Replace the battery if needed.	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	None.
	b. If overfill valve is equipped with mechanical test mechanism, actuate the mechanism to confirm operation	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	None.
3.5 Piping connections	Check for leaks, corrosion and	<input type="checkbox"/> Yes* <input checked="" type="checkbox"/> No	No leaks or corrosion from the exterior.



	damage		
4.0 Tank Attachments and Appurtenances			
4.1 Ladder and platform structure	Secure with no sign of severe corrosion or damage?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No* <input type="checkbox"/> N/A	Ladder Cage and Handrails have minor areas of coating wear.
5.0 Other Conditions			
5.1 Are there other conditions that should be addressed for continued safe operation or that may affect the site spill prevention plan?		<input checked="" type="checkbox"/> Yes* <input type="checkbox"/> No	See recommendations.

Additional Comments: Tank has not been in operation since 2012.



STI SP001 Annual Inspection Checklist

General Inspection Information:

Inspection Date: 6-26-2018	Retain Until Date: (36 months from inspection date)
Prior Inspection Date: Unknown	Inspector Name: Zach Libby
Tank Inspected (ID #): 3	

Inspection Guidance:

- For equipment not included in this standard, follow the manufacturer recommended inspection/testing schedules and procedures.
- The periodic AST inspection is intended for monitoring the external AST condition and its containment structure. This visual inspection does not require a certified inspector. It shall be performed by an owner’s inspector who is familiar with the site and can identify changes and developing problems.
- Remove promptly upon discovery of standing water or liquid in the primary tank, secondary containment area, interstice or spill container. Before discharge to the environment, inspect the liquid for regulated products or other contaminants and dispose of it properly.
- In order to comply with EPA SPCC (Spill Prevention, Control and Countermeasure) rules, a facility must regularly test liquid level sensing devices to ensure proper operation (40 CFR 112.8(c)(8)(v)).
- (*) designates an item in a non-conformance status. This indicates that action is required to address a problem.
- Non-conforming items important to tank or containment integrity require evaluation by an engineer experienced in AST design, a certified inspector, or a tank manufacturer who will determine the corrective action. Note the non-conformance and corresponding corrective action in the comment section.
- Retain the completed checklists for 36 months.
- Complete this checklist on an annual basis supplemental to the owner monthly-performed inspection checklists.
- Note: If a change has occurred to the tank system or containment that may affect the SPCC plan, the condition should be evaluated against the current plan requirement by a Professional Engineer knowledgeable in SPCC development and implementation.

Item	Task	Status	Comments
1.0 Tank Containment			
1.1 Containment structure	Check for: <ul style="list-style-type: none"> • Holes or cracks in containment wall or floor • Washout • Liner degradation • Corrosion • Leakage 	<input checked="" type="checkbox"/> Yes* <input type="checkbox"/> No <input type="checkbox"/> N/A	There are some tight cracks in the containment area walls and floor. The containment floor joints are not sealed and have small scattered areas of foliage growth.



	<ul style="list-style-type: none"> • Paint failure • Tank Settling 		
2.0 Tank Foundation and Supports			
2.1 Foundation	Settlement or foundation washout?	<input type="checkbox"/> Yes* <input checked="" type="checkbox"/> No	No washout or erosion of concrete floor observed.
2.2 Concrete pad or ring wall?	Cracking or spalling	<input checked="" type="checkbox"/> Yes* <input type="checkbox"/> No <input type="checkbox"/> N/A	The viewable areas contained some moderate spalling and erosion.
2.3 Supports	Check for corrosion, paint failure, etc.	<input checked="" type="checkbox"/> Yes* <input type="checkbox"/> No <input type="checkbox"/> N/A	This tank contains seismic anchoring. There was 1 missing bolt noted.
2.4 Water drainage	Water drains away from the tank?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No* <input type="checkbox"/> N/A	Drainage seems ok.
2.5 Tank grounding	Strap secured and in good condition?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No* <input type="checkbox"/> N/A	There is currently no electrical ground installed.

Item	Task	Status	Comments
3.0 Cathodic Protection			
3.1 Galvanic cathodic protection system	Confirm system is functional, includes the wire connections for galvanic systems	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	There are no CP systems in place.
3.2 Impressed current system	a. Inspect the operational components (power switch, meters and alarms).	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	
	b. Record hour meter, ammeter and voltmeter readings.	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	
4.0 Tank Shell, Heads & Roof			
4.1 Coating	Check for coating failure	<input checked="" type="checkbox"/> Yes* <input type="checkbox"/> No	The exterior is insulated. Deteriorated coating could be seen at damaged areas.
4.2 Steel condition	Check for: <ul style="list-style-type: none"> • Dents • Buckling • Bulging • Corrosion • Cracking 	<input checked="" type="checkbox"/> Yes* <input checked="" type="checkbox"/> No	There were some minor dents observed from the interior. There were areas of CUI noted.
4.3 Roof slope	Check for low points	<input type="checkbox"/> Yes* <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	Unable to assess due to spray foam



	and standing water	insulation.
--	--------------------	-------------

Item	Task	Status	Comments
5.0 Tank Equipment			
5.1 Vents	Verify that components are moving freely, and vent passageways are not obstructed for: <ul style="list-style-type: none"> • Emergency vent covers • Pressure/vacuum vent poppets • Other moving vent components 	<input checked="" type="checkbox"/> Yes* <input type="checkbox"/> No	Emergency vent is covered in spray foam. The 3" atmospheric vent is dated.
5.2 Valves	Check the condition of all valves for leaks, corrosion and damage.	<input type="checkbox"/> Yes* <input checked="" type="checkbox"/> No	Valves appear dated but functional.
5.2.1 Anti-siphon check and gate valves	Cycle the valve open and closed and check for proper operation	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	None.
5.2.2 Pressure regulator valve	Check for proper operation. (Note that there may be small, 1/4-inch drain plugs in the bottom of the valve that are not visible by looking from above only)	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	None.
5.2.3 Expansion relief valve	Check that the valve is in the proper orientation. (Note that fuel must be discharged back to the tank via a separate pipe or tubing.)	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	None.
5.2.4 Solenoid valves	Cycle power to valve to check operation. (Electrical solenoids can be verified by listening to the plunger opening and closing. If no audible confirmation, the valve should be inspected for the presence and operation of the plunger.)	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	None.

Item	Task	Status	Comments
5.2.5 Fire and shear valves	a. Manually cycle the valve to ensure components are moving freely and that the valve handle or lever has clearance to allow valve to	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	None.



	close completely.		
	b. Valves must not be wired in open position	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	None.
	c. Make sure fusible element is in place and correctly positioned	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	None.
	d. Be sure test ports are sealed with plug after testing is complete and no temporary test fixture or component remains connected to valve.	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	None.
5.3 Interstitial leak detection equipment	<p>Check condition of equipment, including:</p> <ul style="list-style-type: none"> The window is clean and clear in sight leak gauges. The wire connections of electronic gauges for tightness and corrosion Activate the test button, if applicable. 	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	Single wall AST.

Item	Task	Status	Comments
5.4 Spill containment boxes on fill pipe	a. If corrosion, damage, or wear has compromised the ability of the unit to perform spill containment functions, replace the unit.	<input type="checkbox"/> Yes* <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	None.
	b. Inspect the connections to the AST for tightness, as well as the bolts, nuts, washers for condition and replace if necessary.	<input type="checkbox"/> Yes* <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	None.
	c. Drain valves must be operable and closed	<input type="checkbox"/> Yes* <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	None.
5.5 Strainer	a. Check that the strainer is clean and in good condition	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	None.
	b. Access strainer basket and check cap and gasket seal as well as bolts.	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	None.
5.6 Filter	a. Check that the filter is in good condition and is within the manufacturer's expected	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	None.



	service life. Replace, if necessary.		
	b. Check for leaks and decreased fuel flow.	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	None.
5.7 Flame arrestors	Follow manufacturer's instructions. Check for corrosion and blockage of air passages.	<input type="checkbox"/> Yes* <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	None.
5.8 Leak detector for submersible pump systems	Test according to manufacturer's instructions and authority having jurisdiction (AHJ). Verify leak detectors are suited and properly installed for aboveground use.	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	None.

Item	Task	Status	Comments
5.9 Liquid level equipment	a. Has equipment been tested to ensure proper operation	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	All related components and device appear removed or offline.
	b. Does equipment operate as required?	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	
	c. Follow manufacturer's instructions	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	
5.10 Overfill equipment	a. Follow manufacturer's instructions and regulatory requirements for inspection and functionality verification.	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	No overfill alarms observed.
	b. Confirm device is suited for above ground use by the manufacturer	<input type="checkbox"/> Yes <input type="checkbox"/> No* <input checked="" type="checkbox"/> N/A	
6.0 Insulated Tanks			
6.1 Insulation	Check condition of insulation for: <ul style="list-style-type: none"> • Missing sections • Areas of moisture • Mold • Damage 	<input checked="" type="checkbox"/> Yes* <input type="checkbox"/> No <input type="checkbox"/> N/A	There were many suspect CUI (corrosion under insulation) areas throughout the exterior of the shell due to various openings and damage within the jacketing. Internal UT testing was performed on the shell interior of course 1 and 2 confirming that external metal loss up 0.06" has occurred in some locations. The external shell was also visible through UT ports that were installed during this inspection, and there appears to be a heavily degraded coating present in the upper courses of the tank.
6.2 Insulation cover or jacket	Check for damage that will allow water intrusion	<input checked="" type="checkbox"/> Yes* <input type="checkbox"/> No <input type="checkbox"/> N/A	See above.
7.0 Miscellaneous			
7.1 Electrical wiring and boxes	Are they in good condition?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No* <input type="checkbox"/> N/A	Intact wiring appeared satisfactory.



7.2 Labels and tags	Ensure that all labels and tags are intact and readable.	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No* <input type="checkbox"/> N/A	Labels were legible. There is no data plate installed.
---------------------	--	---	--

Additional Comments: See recommendations in section 4.0. This tank qualifies as a category 1 since it has spill control, continuous release detection and a release prevention barrier due to the double bottom design, raised foundation and secondary containment.



8.0 Photographs





Coupling B



Coupling C



Suction Nozzle D



Sample Point J





Transfer Nozzle E



Deteriorated Insulation at Nozzle Penetration.



Missing Anchor Bolt



Ladder Base





Dead Space Cut Out



Shell Jacket Hole



Edge of Foundation Pad



Nozzle G





Nozzle H



Shell Insulation Bands



Nozzle I



Sensor Control Station





Floor Overview



Roof Interior View



Manway A Neck




Internal 3 Way Lap





Floor Coating Failure



Shell Internal Coating Failure



Lower Shell Large Coating Failure



Shell Patch





Steam Nozzle I



Temp Quill B



Coupling C



Suction Nozzle D Interior





Coupling J Interior



Nozzle G Interior. Note Coating Degradation



Shell Jacketing Hole



Broken U Bolt





Emergency Vent AF and Roof Overview



Shell Top Angle. Note Opening.



Old Autogauge Details



Roof Overview





Emergency Vent



Vent AG



Vent Stem



Nozzle AA





9.0 NDE Equipment Used

The equipment utilized for the inspection of the tank included of the following :

Pit Gauge

Manufacturer	Model	Serial No
W.R. Thorpe	1	1.979.912

Ultrasonic Transducers


Manufacturer	Model	Serial No	MHz	Diameter
Olympus	D790-SM	865199	5	0.375

UT Equipment

Manufacturer	Model	Serial No
Olympus	38DL Plus	130573601
CS Cal. Block	0.100-0.500	96-7601




10.0 Inspector Certifications






11.0 Drawings

TANK 3 ELEVATION NORTH DRAWING




CUSTOMER: ECOLUBE	SHELL HEIGHT: 36'	DIAMETER: 10'	INSPECTION DATE: 06/26/19	 MISTRAS <small>A World of NDT Solutions</small>
LOCATION: PUYALLUP	INSPECTOR: ZACH LIBBY		DRAWING NUMBER: TANK 3 ELEV.	
TANK NUMBER: TANK 3	TECHNICIAN: BRANDON GONZALEZ		CAD DRAFTSMAN: B. GONZALEZ	7820 S 210th Street, Building C, Suite 110 KENT, WA 98032

TANK 3 ROOF DRAWING


STAIRS

LADDER



LEGEND & NOTES

XXX ULTRASONIC THICKNESS READING IN THOUSANDTHS OF AN INCH OF THE PLATE. IT DOES NOT INCLUDE ANY PAINT OR COATING THICKNESS.

CUSTOMER: ECOLUBE	SHELL HEIGHT: 36'	DIAMETER: 10'	INSPECTION DATE: 06-29-19
LOCATION: PUYALLUP, WA	INSPECTOR: ZACH LIBBY	DRAWING NUMBER: TANK 3 ROOF	
TANK NUMBER: 3	TECHNICIAN: BRANDON GONZALEZ	CAD DRAFTSMAN: B. GONZALEZ	
			
7820 S 210th Street, Building C, Suite 110 KENT, WA 98032			



ChemE Consulting, LLC

9021 Willow Grove Rd

Longview, WA 98632

David@Chemeconsulting.com / 360-355-5513

Appendix 2

Structural Anchor Review – Conlee Engineers



CONLEE
ENGINEERS, INC.

Client CES
Project RYALLUP TANK REV.
Subject TANK 3

Sheet T3.1
Date 9.12.21
By CJC

TANK 4, 71'φ × 36', 25,580 GAL, 3-1 1/4"φ AB

Tank

$$TAB @ \frac{\pi (11)^2}{4} 10.2 (2) = 1.94^k$$

$$WML @ \pi (11) 36 (10.2) = \frac{12.69^k}{W_{TANK} = 14.63^k}$$

CONTENTS 25,580 GAL OIL

$$W_{OIL} = 25,580 (7.3 \frac{lb}{gal}) = 186.7^k \rightarrow$$

SEISMIC W/Cs = 0.28

$$E = 0.28 (14.63 + 186.7) = 56.37^k$$

$$M = 56.37^k (18') = 1015^{k-ft}$$

SECTION w/ D₁ = 132", D₂ = 130"

$$A = \frac{\pi}{4} (132^2 - 130^2) = 411.6 \text{ in}^2$$

$$S = \frac{\pi}{32} \left(\frac{132^4 - 130^4}{132} \right) = 13,377 \text{ in}^3$$

LOADS w/ 0.9D + E

$$f_a = 0.9 \frac{(14.63 + 186.7)}{411.6} = 0.44 \text{ ksi}$$

$$f_b = \frac{1015 (12)}{13,377} = 0.91 \text{ ksi}$$



$$f_t = 0.44 - 0.91 = -0.47 \text{ ksi}$$

w/ 3-BOLTS, TRIB = π(11)12 = 510"

$$\sqrt{F} = \frac{56.37^k}{510} = 7.05 \frac{lb}{bolt}$$

$$T = 0.47 \text{ ksi} (510') = 24.55^k/B$$

Assume 9 1/2' EMBED.



CL EXIST. ANCHORS (CONT)

1 Input data

Anchor type and diameter: Heavy Hex Head ASTM F 1554 GR. 36 1 1/4

Effective embedment depth: $h_{ef} = 9.500$ in.

Material: ASTM F 1554

Proof: Design method ACI 318-08 / CIP


Stand-off installation: $e_o = 0.000$ in. (no stand-off); $t = 0.500$ in.

Anchor plate: $l_x \times l_y \times t = 5.000$ in. \times 5.000 in. \times 0.500 in.; (Recommended plate thickness: not calculated)

Profile: S shape (AISC), S3X5.7; (L x W x T x FT) = 3.000 in. \times 2.330 in. \times 0.170 in. \times 0.260 in.

Base material: cracked concrete, 3000, $f'_c = 3,000$ psi; $h = 24.000$ in.

Reinforcement: tension: condition B, shear: condition B; edge reinforcement: none or $<$ No. 4 bar



2 Proof | Utilization (Governing Cases)


Loading	Proof	Design values [lb]		Utilization	Status	
		Load	Capacity	P_n / P_v [%]		
Tension	Concrete Breakout Strength	24,360	26,944	91 / -	OK	
Shear	Steel Strength	7,050	21,919	- / 33	OK	
Loading		P_n	P_v	ζ	Utilization $[P_{n,v}]$ [%]	Status
Combined tension and shear loads		0.904	0.322	5/3	100	OK

I.R. = 100% % EXIST. ANCH. OK

OK. REPLACEMENT ANCHOR
1 1/4" THRU. ROD IN FLOW ANCH 13" EMBED

1 Input data

Anchor type and diameter:	HIT-RE 500 V3 + HAS-V-36 (ASTM F1554 Gr.36) 1 1/4
Effective embedment depth:	$h_{ef,act} = 13.000$ in. ($h_{ef,limit} = -$ in.)
Material:	ASTM A 1554 Grade 36
Evaluation Service Report:	ESR-3814
Issued Valid:	1/1/2020 1/1/2021
Proof:	Design method ACI 318-08 / Chem
Stand-off installation:	$e_b = 0.000$ in. (no stand-off); $t = 0.500$ in.
Anchor plate:	$l_x \times l_y \times t = 5.000$ in. \times 5.000 in. \times 0.500 in.; (Recommended plate thickness: not calculated)
Profile:	S shape (AISC), S3X5.7; (L x W x T x FT) = 3.000 in. \times 2.330 in. \times 0.170 in. \times 0.260 in.
Base material:	cracked concrete, 3000, $f'_c = 3,000$ psi; $h = 24.000$ in., Temp. short/long: 32/32 °F
Installation:	hammer drilled hole, Installation condition: Dry
Reinforcement:	tension: condition B, shear: condition B; no supplemental splitting reinforcement present edge reinforcement: none or < No. 4 bar



Professional Engineer Seal
 9-19-21

2 Proof | Utilization (Governing Cases)

Loading	Proof	Design values [lb]		Utilization	Status	
		Load	Capacity	P_n / P_r [%]		
Tension	Concrete Breakout Strength	24,360	28,369	86 / -	OK	
Shear	Steel Strength	7,050	21,921	- / 33	OK	
Loading		P_n	P_r	ζ	Utilization $P_{n,v}$ [%]	Status
Combined tension and shear loads		0.859	0.322	5/3	93	OK



ChemE Consulting, LLC

9021 Willow Grove Rd

Longview, WA 98632


David@Chemeconsulting.com / 360-355-5513

Appendix 3


Drawings

APPLICABLE FIRE CODE REQUIREMENTS

Chapter 50 - Hazardous Materials Classification for Base Oil & Antifreeze	
Combustible Liquid - Class IIIB	
Use - Storage	
Base Oil (Lubricating Motor Oil CAS # - 64742-58-1)	Combustible Liquid - Class IIIB - Storage
Antifreeze 50% & 100% (Ethylene Glycol CAS# 107-21-1)	Combustible Liquid - Class IIIB - Storage
Wiper Fluid 8% Methanol CAS# 67-56-1 in DI Water	Not Applicable: Solutions with <20% liquid in water and Flash Point >95F (IFC 5701.2.8) are exempt
Maximum allowable quantity (MAQ) per control area - Table 5003.1.1(3)	
MAQ - Class IIIB Combustible Liquid = 13,200 gal	Storage tank volume above MAQ
Requirements for Chapter 50 - Hazardous Materials	
Safety Data Sheet	SDS for N100 Base Oil, Antifreeze, Wiper Fluid attached
Spill Mitigation	Spill containment system provided
Ignition of Hazards	Area to be kept clear of ignition hazards
Protection of hazardous materials	The tank are located with concrete containment area with walls
Exposure hazards from fire	Containment area is kept free of flammable materials
Detection of Gas Release	No hazardous gas potential associated with base oil
Reliable power	Power will be installed under electrical permit
Ventilation	Oil and antifreeze do not have vent fumes due to vapor pressure which would require additional ventilation.
Operating and emergency plans	Operating, safety and emergency plans will be developed for the plant
Design of tanks	Existing carbon steel tank inspected and modified to meet UL-142
Protection of tanks	Tanks are located within concrete containment and berm walls
Tank Marking	Tanks are labelled with NFPA or HMIS labels
Tank Venting	Each tank will be provided one 3-inch tank vent provided for normal venting with 10" emergency vent for existing tanks. HDPE tanks will be provided 3" vent for combined normal and emergency venting.
Tank Seismic protection	Existing tanks have seismic anchors and additional anchoring will be added per inspection reports. HDPE tank anchors per manufacturer designs will be installed with tanks.
Design of piping	Piping installed to ASME B31.3
Liquid - level indication	Carbon steel and stainless connections are welded.
Liquid - level limit control	Tanks will be equipped with level transmitter for display of tank level and gauges for new HDPE tanks
Maintenance Testing	Tanks will be equipped with high-high level pump shutoff with auto closure valves on flow to HDPE tanks.
Instrument Testing	Equipment will be inspected and tested on routine frequency
Signage	Liquid level control will be tested annually
Tanks shall have hazard identification signage	Tank to be labelled with NFPA 704 or HMIS labels
Tanks shall be labeled	Tank markings include Tank ID and Contents
"No Smoking Signs" are required within 25 feet of outdoor storage	Signage is provided on containment wall
Pipe labelling	Pipe labelling to include material and line number designation
Personnel training is required	Operating personnel will be trained on procedures
Security is provided against unauthorized entry	Site is fenced and gated
Protection from vehicle damage	Tank is located within concrete walled containment
Electrical Wiring	Wiring is being installed to electrical code under permit per NFPA 70
Separation of Incompatible materials	Incompatible materials are not stored in common containment areas
Control Area in free of weeds for 15 feet	Area outside of containment area is kept clear of weeds
Spill control and containment is required for Class IIIB Combustible Liquids exceeding 13,200 gallons.	Concrete containment with sumps is provided. Some containment concrete upgrades to seal cracks will be completed.
Containment volume must be larger than tank plus 25-yr/24-hr storm	Maximum Tank Volume = 30,000 gal (Tank 4) Required Rain Volume 3.8" Source NOAA 100yr - 24 Hour Event = 4,321 gal outside Total Required Volume = 34,321 gal Actual Containment Volume = 35,409 gal
Monitoring sump	Sumps are pumped to wastewater treatment (POTW Permit application pending)
Limit Controls	Tank is stored at ambient temperature and pressure in vented tanks without heating
Lighting	Indoor/Outdoor Lighting is provided for detection of leaks and operability
Siphon Protection	Base oil tanks are top loaded to prevent siphon potential. Check valves are used in Antifreeze transfer piping.
Additional Requirements for Chapter 57 - Combustible Materials	NFPA 30 incorporated by reference.
See secondary containment above	
See Signage above	
See Piping Systems above	
Pressure testing of piping	Oil piping is pneumatically tested to 110% of design pressure or hydraulically tested to 150%
See Protection from vehicles above	
Protection from Corrosion	Exterior carbon steel components will be painted to protect equipment from corrosion
Providing sufficient number of valves	Sufficient number of manual and automated valves are provided to control the process
See sources of ignition above	
See separation of incompatible materials above	
Design tanks to comply with NFPA 30 for materials	NFPA 30 allows use of metal or non-metal tanks for Class IIIB. The tank is designed to UL-142
Design tanks to comply with NFPA 30 for marking	Tanks have embedded designation of serial number, manufacture date, and capacity.
Design tanks to comply with NFPA 30 for venting	See tank venting requirements above.
See Overfill Protection above	
Tank Anchoring	See tank anchoring requirements above.
Setback from property line or public way is >10 feet (NFPA 30- Table 22.4.1.6)	Setback requirement for largest tank of 30,000 gal at atmospheric pressure - Setback is 17'-6"



PLAN NORTH
OVERALL SITE PLAN
NOT TO SCALE



PLAN NORTH
TANK AREA PLAN
NOT TO SCALE

Project Description
An additional existing carbon steel single-wall tank is proposed to be repurposed for service under minor modification to the CUP to be added to the 6 other metal tanks previously repurposed and three HDPE tanks for storage of Class III-B combustible materials as part of CUP project. There will be 4 tanks outdoors instead of 3 used for storage of Used Motor Oil (UMO) and three tanks indoors will be used for the storage of concentrated antifreeze or spent antifreeze. The smaller HDPE tanks will be used for 50% antifreeze blend tanks used to fill containers. Tank 3 will be upgraded to address all deficiencies listed by Mistras Group for compliance with UL 142 combustible liquid storage including anchoring, level monitoring and overfill protection and containment. New piping will connect existing unloading and loading manifolds to Tank 3.


Reference Permits
City of Puyallup Conditional Use Permit No. P-18-0154
City of Puyallup Civil Permit - E-20-0114
City of Puyallup Fire Construction Permit Sprinklers - F-20-0039
City of Puyallup Fire Construction Permit Fire Alarm System - Under Review
City of Puyallup - Tenant Improvement - Bdg Permit B-15-0254

Applicable Codes and Standards
International Fire Code - 2018
International Building Code - 2018
International Mechanical Code - 2018
NFPA 30 - Flammable and Combustible Liquid Code
ASME B31.3 - Process Piping Code


LOCATION DESIGNATORS

A	LOCATION OF "NO SMOKING SIGNAGE"
B	LOCATION OF TANK SIGNAGE
C	LOCATION OF CONCRETE WALLS
D	LOCATION OF FIRE EXTINGUISHERS

Ecolube Tank #	Volume (Gallons)	Dimensions	Material	Product
1	25,454	10'-7" Dia x 40' H	Carbon Steel	Motor Oil (sg=0.875)
2	25,454	10'-7" Dia x 40' H	Carbon Steel	Motor Oil (sg=0.875)
3	29,610	11'-0" Dia x 36' H	Carbon Steel	Motor Oil (sg=0.875)
4	30,000	10'-0" Dia x 49.5' H	Carbon Steel	Motor Oil (sg=0.875)
7	24,881	11'-0" Dia x 36' H	Carbon Steel	Spent Antifreeze (sg=1.11)
8	19,430	10'-7" Dia x 30' H	Stainless Steel	Antifreeze (sg=1.11)
9	19,430	10'-7" Dia x 30' H	Stainless Steel	Antifreeze (sg=1.11)
12	1,500	5'-4" Dia x 9'-8" H	poly	50% Antifreeze (sg=1.07)
13	1,500	5'-4" Dia x 9'-8" H	poly	50% Antifreeze (sg=1.07)
14	6,100	9'-11" Dia x 11'-8" H	poly	50% Antifreeze (sg=1.07)



												ECOLUBE RECOVERY 213 10TH ST SE PUYALLUP, WA 98731		USED OIL AND ANTIFREEZE TANKS FIRE CODE REVIEW TANK 3 CUP MINOR MODIFICATION																	
No.	DRAWING	REFERENCE	No.	DRAWING	REFERENCE	No.	DRAWING	REFERENCE	No.	DATE	REVISION	DR.	CH.	AP.	No.	DATE	REVISION	DR.	CH.	AP.	DR.	CH.	AP.	SCALE:	AS SHOWN	DATE:	11/09/20	DWG. No.	FS - 001	REV.	0



LEGEND
 — TANK 3
 — RELOCATED / REUSED EQUIPMENT

PLAN NORTH
 ↑
 PIPING PLAN
 NOT TO SCALE

No.	DRAWING	REFERENCE	No.	DRAWING	REFERENCE	No.	DRAWING	REFERENCE	No.	DATE	REVISION	DR.	CH.	AP.	No.	DATE	REVISION	DR.	CH.	AP.	No.	DATE	REVISION	DR.	CH.	AP.

	ECOLUBE RECOVERY 213 10TH ST SE PUYALLUP, WA 98731	USED OIL AND ANTIFREEZE TANKS PIPING LAYOUT DRAWING TANK 3		
	DRAWN: DR CHECKED: BB	SCALE: AS SHOWN APPROVED:	UN: . DATE: 11/09/20	DWG. No. P - 106