

City of Puyallup **Engineering Division** 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

## **INSPECTION REPORT**

Mar 08, 2023	Inspection Result:	FAILED
E-20-0612 3213 WILDWOOD PARK	DR, PUYALLUP, WA 983	74;
	E-20-0612 3213 WILDWOOD PARK PEASE & SONS PO BOX 10601 Waller Rd E Tacc CIVILS ~ FERRUCCI JHS F	E-20-0612 3213 WILDWOOD PARK DR, PUYALLUP, WA 983 PEASE & SONS PO BOX 44100 TACOMA, WA 9 10601 Waller Rd E Tacoma, WA 98446 (253) 37 CIVILS ~ FERRUCCI JHS REMODEL & ADDITION*

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** No erosion control has been installed around the exposed soils at the ball field. Silt has entered the French drain see daily inspection on 3/8. There are many areas throughout the site where erosion is happening. Hydro seed is washing off, slopes have rills, plastic has blown off slopes, and track out are just some of these problems. In documents and images file name Ferrucci E&S has 81 pictures of erosion problems. Fix all erosion issues to lift the stop work order. I spoke with Pease & son and asked for the CESCL reports for their NPDES permit with DOE. they where unable to provide these reports that are supposed to be onsite at all times.

## Corrections:

- 1 install erosion control measures around the exposed soils in the ball field.
- 2 Fix all erosion control issue throughout site.
- 3 Provide the CESCL reports from the DOE NPDES permit

Sincerely,

Jeff Hill Engineering Tech IV Jhill@PuyallupWA.gov (253) 841-5424



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org