

CORRECTION RESPONSE LETTER

Greetings,

A new TCP has been uploaded that addresses all the problems with the previous submission. Site specific TCPs have been provided as requested for the intersections of Pioneer and 21st St SE, Pioneer and 25th St SE, and Pioneer east of Shaw Rd E.

Valley View Dr is wide enough to have one lane open while using flaggers. The new TCP states that the contractor is responsible to maintain a 10' lane for traffic.

The new TCP shows that a flagger must control east bound 7th Ave SE traffic

Comments about shifting cones and road closures have been removed as requested at certain locations.

In order for flaggers to control E Pioneer properly the new TCP shows the outside lane in each direction closed prior to the intersection.

To prevent drivers from making a turn onto 25th, the TCP shows that the road will be closed and a detour will be put in place. There will be customer outreach to inform residents of the road closure prior to work start.

Regards,
Matthew Bateman
PSE Regional Arborist