

**Woodland Gardens Construction, INC.**  
 7317 124th Street E • Puyallup, WA 98373  
 253-405-0888

**BACKFLOW PREVENTION ASSEMBLY TEST REPORT**

NAME OF PREMISE HAMPTON Inn & SUITES Commercial  Residential   
 SERVICE ADDRESS 1515 S MERIDIAN CITY Puyallup ZIP 98371  
 CONTACT PERSON \_\_\_\_\_ PHONE (\_\_\_\_) \_\_\_\_\_ FAX (\_\_\_\_) \_\_\_\_\_  
 LOCATION OF ASSEMBLY EAST SIDE OF BUILDING  
 PREMISE ISOLATION  (or) IN-PREMISE ISOLATION \_\_\_\_\_  
 DOWNSTREAM PROCESS HOTEL DCVA  RPBA  PYBA  OTHER \_\_\_\_\_  
 NEW INSTALL  EXISTING  REPLACEMENT  OLD SER. # \_\_\_\_\_ PROPER INSTALLATION? YES  NO   
 MAKE OF ASSEMBLY Ppollo MODEL OKLF4A SERIAL NO. 49753C SIZE 2.0"

INITIAL TEST	DCVA / RPBA CHECK VALVE NO. 1			DCVA / RPBA CHECK VALVE NO. 3			RPBA			PYBA/SYBA AIR INLET		
	LEAKED <input type="checkbox"/>	PSID		LEAKED <input type="checkbox"/>	PSID		OPENED AT	PSID		OPENED AT	PSID	
PASSED <input checked="" type="checkbox"/> FAILED <input type="checkbox"/>	<u>2.1</u>			<u>1.8</u>			#1 CHECK			DID NOT OPEN	<input type="checkbox"/>	
NEW PARTS AND REPAIRS	CLEAN <input type="checkbox"/> REPLACE <input type="checkbox"/> PART _____			CLEAN <input type="checkbox"/> REPLACE <input type="checkbox"/> PART _____			CLEAN <input type="checkbox"/> REPLACE <input type="checkbox"/> PART _____			CHECK VALVE HELD AT		
TEST AFTER REPAIRS	LEAKED <input type="checkbox"/>			LEAKED <input type="checkbox"/>			OPENED AT			CLEANED REPAIRED	<input type="checkbox"/>	
PASSED <input type="checkbox"/> FAILED <input type="checkbox"/>							#1 CHECK			AIR INLET		
										CHK VALVE		

AIR GAP INSPECTION: Reported minimum air gap (separate provided)? Yes  No  Detector Meter Reading \_\_\_\_\_  
 REMARKS: \_\_\_\_\_

TESTERS SIGNATURE: [Signature] CONTAINED SPACE? NO LINE PRESSURE 105 PSI  
 TESTER'S NAME (PRINTED): JASON ANDERSON CERT. NO. 83354 DATE 7.31.24

REPAIRED BY: \_\_\_\_\_ TESTER'S PHONE # ( 253 ) 405-0888

FINAL TEST BY: \_\_\_\_\_ DATE \_\_\_\_\_  
 CERT. NO. \_\_\_\_\_ DATE \_\_\_\_\_

CALIBRATION DATE 11/15/23 GAUGE # 10140894 MODEL 845 SERVICE RESTORED? YES  NO

I certify that this report is accurate, and I have used WAC 516-190-020 approved test methods and test equipment.