



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Dec 12, 2024 **Inspection Result:** **FAILED**

Permit Number: PRCCP20241189

Property Address: 110 9TH AVE SW, Unit: 10, PUYALLUP, WA 98371; 902 S MERIDIAN, Unit:
6, PUYALLUP, WA 98371;

Contractor: MOUNTAIN CONSTRUCTION INC. 7457 S MADISON TACOMA, WA
98409

To construct: Redevelopment includes demolition of existing International Village building; and construction of a new two-story restaurant in place. Site improvements include power, gas, and communication service connections, installation of detention tank to manage roof runoff, and installation of permeable pavements to manage new hardscape. Improvements also include reroute of fire and domestic water service to the building. - WSF INTERNATIONAL VILLAGE REDEVELOPMENT

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: The native soils used for backfill is being tracked through out the site. All soils not being work must be covered. The native backfill in the drive areas should be lowered and road base installed in its place. This will eliminate the track out issue.

Corrections:

- 1 cover all soils not in use.
- 2 remove the top of the native soils in the trench lines. replace with road base.

Sincerely,

Jeff Hill
Development Engineering Inspector



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

Jhill@PuyallupWA.gov

(253) 204-5633