



City of Puyallup

**Engineering Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

## INSPECTION REPORT

**Date of Inspection:** Jan 24, 2025

**Inspection Result:** **FAILED**

**Permit Number:** PRCCP20241189

**Property Address:** 110 9TH AVE SW, Unit: 10, PUYALLUP, WA 98371; 902 S MERIDIAN, Unit: 6, PUYALLUP, WA 98371;

**Contractor:** MOUNTAIN CONSTRUCTION INC. 7457 S MADISON TACOMA, WA 98409

**To construct:** Redevelopment includes demolition of existing International Village building; and construction of a new two-story restaurant in place. Site improvements include power, gas, and communication service connections, installation of detention tank to manage roof runoff, and installation of permeable pavements to manage new hardscape. Improvements also include reroute of fire and domestic water service to the building. - WSF INTERNATIONAL VILLAGE REDEVELOPMENT

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** When I arrived onsite the contractor was potholing for the water main tie in. The contractor was pumping out turbid ground water directly into the existing storm system. Final warning given about dewatering dirty water into the storm system. The native soils are still being tracked around the site and are making it to the existing catch basins. See Corrections.

**Corrections:**

- 1 cover all soils not in use.
- 2 remove the top of the native soils in the trench lines. replace with road base.
- 3 clean out CB socks

Sincerely,



City of Puyallup

---

**Engineering Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

Jeff Hill

Development Engineering Inspector

[Jhill@PuyallupWA.gov](mailto:Jhill@PuyallupWA.gov)

(253) 204-5633