

City of Puyallup **Building Division** 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

PRDK20241969

Permit Review Correction Letter

Permit Application #PRDK20241969

January 10, 2025 January 20, 2025 CDA Response in bold italics

The City has completed the review of the above-mentioned permit submittal. All your review comments, conditions, and redlined plans can be found on the <u>City's permit portal</u>. Redlined plans can be found on the City's Permit Portal in the "Reviews" section under "Documents Returned for Corrections". Below please find the permit submittal review comments from your review team and resubmittal instructions. Should you have any questions regarding the review comments, please contact the plan reviewer associated with the comment listed below.

Corrections

Corrections to be addressed on the next set of resubmitted plans:

Building Review	Stan Kinnear	SKinnear@puyallupwa.gov			
specifics that will reflect th surface that will either be p	at the plywood will withstand the d	nould include plywood thickness, grade and any other ead and live loads of the deck. Identify the non-slip dded to the plywood as part of construction, as			
CDA Response: The plywoo dead loads is attached to t	-	l slip resistance information and span chart for live &			
The existing joist spacing sh provide the existing joist sp		ting the plywood material that will be used. Please			
CDA Response: Existing joi	st spacing is 16″ o.c. max.				
Updated all details and not	es as needed to reflect the requeste	d information.			
CDA Response: Details upo	lated with information as required.				
shows the installation of th	loped to drain off of the cantilevere	d side of each deck based upon details 1 and 2. Detail 2 2x2 balusters. detail or notate how the 1x6 cedar will e deck surface.			
CDA Response: There will l	be a space between the existing 2x2	pickets for water to drain off deck.			
	Sheet A1.0 or A1.1 that contractor s	nall verify the integrity of balusters prior to the Ilusters replacement to include type, grade and nailing			
CDA Response: Note addea fasteners.	l to details to review integrity of exis	ting 2x2 pickets and replace with like materials and			
(Construction Plans, Sheet A1.1) - Detail the connection between the existing and proposed slab.					
CDA Response: Connection	not necessary. New slab is not struc	tural.			
- (Construction Plans, Shee	t A1.1, Detail 1a)				

Engineering Review	Adam Hunt	(253)841-5577	AHunt@PuyallupWA.gov
- NO COMMENTS AVAILABLE - Place street names on site p		<u> </u>	
CDA Response: Street names	have been added to the site mo	ap.	

Conditions

The items listed in the table below are conditions of the permit that do not need to be addressed on the next resubmittal of plans but will need to be fulfilled at some point in the permit review process. The "Condition Category" indicates the approximate phase of the permit process by which the

condition must be fulfilled for the City to continue processing this permit. "Condition Status" if "Open" means that the condition has not been fulfilled, if "Resolved" means the condition has been fulfilled successfully. For some conditions that require submittal of a document to the City, those documents can be submitted via the Conditions Section of the <u>City's permit portal</u>.

Condition	Condition	Department	Condition
Category			Status

If you need assistance with resubmitting your corrections, please contact the Permit Center.

Sincerely,

City of Puyallup Permit Center (253) 864-4165 option 1 permitcenter@puyallupwa.gov

Casey+DeChant Architects LLC

Larry DeChant – Architect (253) 677-0364