



**CARUSO  
TURLEY  
SCOTT**  
structural  
engineers

STRUCTURAL  
ENGINEERING  
EXPERTS

PARTNERS

Sandra Herd, SE, PE, LEED AP  
Thomas Morris, SE, LEED AP  
Richard Dahlmann, SE, PE  
Troy Turley, SE, PE, LEED AP  
Brady Notbohm, SE, PE

PROFESSIONAL  
REGISTRATION

All 50 States  
Washington D.C.  
Puerto Rico

May 13, 2025

**Sarah Jacobson**  
Fuzion  
9096 E. Bahia Dr.  
Scottsdale, AZ 85260

**RE: T-Mobile #8022 TI**  
4227 S. Meridian, Suite E  
Puyallup, WA  
CTS Job No. 24-1374

**PRCTI20241902**



Dear Ms. Jacobson,

The following edits have been made to the structural drawings as part of Delta 2: Structural Revisions

**Sheet S201:** The roof framing plan has been updated to show a truss being headered off to allow space for the ductwork. The truss will be cut and a new 2x12 wood joist will be sistered onto the truss to support the existing roof loads. This 2x12 joist will be supported by new 4x12 headers that span between the 18" deep glulam wood beams as shown on the plan.

**Sheet S102, Detail 14:** The truss being headered off has been notated as such. Additionally, the new 2x12 wood joist supporting the roof loads in place of the truss has also been shown.

**Sheet S102, Detail 17:** This detail has been added to show how to attach the new 2x12 wood joist to both the truss being headered off and the 4x12 wood header beam.

Please contact our office with any questions or comments at 480.774.1700.

Respectfully submitted,  
**CARUSO TURLEY SCOTT**

Jacob Conerly  
Structural Designer  
480.774.1708 Direct  
jconerly@ctsaz.com

Reviewed By:



Troy Turley, SE, PE, LEED-AP  
Partner