



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Jan 27, 2022

Inspection Result: PARTIAL PASS

Permit Number: B-21-0544

Property Address: 4423 S MERIDIAN;

Contractor: PROBUILD CONSTRUCTION 12112 92ND AVE CT E PUYALLUP, WA
98373 Alex Rodriguez 12112 92ND AVE CT E SOUTH HILL, WA 98373
(253) 844-7547

To construct: TI ~ TANDOORI GRILL

BLDG/PLUMB/MECH

On this day we have inspected your construction for **Grease Interceptor Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: INSP GREASE INTERCEPTOR - 11.03.21 The grease interceptor must be brought to current standards to ensure proper function. Occupancy shall not be granted until the grease interceptor has been cleaned thoroughly and inspected for damages. In addition, the grease interceptor must be properly vented and a sampling cleanout installed downstream of the grease interceptor if not present. YC

- Replace 6" fernco's for the sampling tee (outlet), replace 3" pvc with 4" pvc and add a c/o at the building, stub 4" into GI so that it can be seen through the

Corrections:

Sincerely,



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

Jason Little
Engineering Tech IV
JLittle@PuyallupWA.gov
(253) 435-3636