City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Permit Number: E-21-0068

Property Address: 3500 S MERIDIAN

Contractor: ROD BANE MANAGEMENT DBA RBM 6668 E OLIVE AVE FRESNO, CA

93727

To construct: GREASE INTERCEPTOR~ ROUND 1 BOWLING & AMUSEMENT

On this day we have inspected your construction for **Engineering Daily Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: AA Advanced cleaned up the lids, the fire vault (full of water), installed the upright for the vent (not mounted).

- 1. Landscape area needs to be stabilized back to original condition.
- 2. PIV tamper switch needs to be repaired and tested per fire code.
- 3. Fire vault needs to be pumped and existing pump needs to be operational.
- 4. Tamper switches in vault need to be tested and operational.
- 5. GI vent needs to be properly mounted to the wall.

_					
(:n	rre	cti	ın	ns	٠.


Sincerely,



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org



Jason Little Engineering Tech IV JLittle@PuyallupWA.gov (253) 435-3636