City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Oct 25, 2022 Inspection Result: FAILED

Permit Number: E-20-0070

Property Address: 3601 9TH ST SW;

Contractor: THARALDSON HOSPITALITY DEV LLC 4520 36TH AVE S FARGO, ND

58104

To construct: CIVILS ~ HOMEWOOD SUITES SOUTH HILL MALL MOTEL**2021 STORM

SDC FEES UPDATED**APP EXT TO 12/30/21 BLDG PERMIT B-20-0180

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: There is sediment leaving the site at the construction entrance and heavy sediment entering the on site storm system.

Note: Silt socks are last resort protection.

Corrections:

- 1 1st warning!
 - 1. Keep silt runoff on site.
 - 2. Keep silt run off from entering the existing storm on site.
 - 3. Protect the on site existing storm with multiple BMP's to ensure no silt enters the existing storm system. This will result in an entire surrounding site extensive storm cleaning.


Sincerely,



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org



Jason Little Engineering Tech IV JLittle@PuyallupWA.gov (253) 435-3636