City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Sep 19, 2023 Inspection Result: FAILED

Permit Number: PRFUP20231157

Property Address: 115 2ND ST SE, PUYALLUP, WA 98372;

Contractor: COMCAST - SEFNCO 410 VALLEY AVE #101 NW PUYALLUP, WA 99999

To construct: JB0001481240 Comcast proposes to de/relash aerial fiber 162 lf;

overlash aerial fiber 450 lf; and also riser down and proof an pull fiber

through existing conduit 195 If

On this day we have inspected your construction for **Comment Engineering Div Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: Note: Comcast, JB0001481240, it is very important that the field crew has the City approved TCP. This TCP has very important comments. The comments are very colorful and easy to read.

Tonight, the field crew DID NOT have the city approved TCP on site. This has occurred on multiple projects in the past!

If this happens again there will be an added inspection fee of 130\$ AND the crew WILL NOT be allowed to work!

Thank you for your cooperation from here on out.

	_									
ı	١.	n	rr	Д	СT	ш	n	n	C	١


Sincerely,



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org



Jason Little Engineering Tech IV JLittle@PuyallupWA.gov (253) 435-3636