

Corrections

Corrections to be addressed on the next set of resubmitted plans:

| Engineering Review | Linda Lian | (253)841-5577 | LindaL@PuyallupWA.gov |
|---|------------|---------------|-----------------------|
| <ul style="list-style-type: none">- A TCP was not submitted for this location [Site Plan Sheet 2 of 2 Design View - 1]- A TCP was not submitted for this location [Site Plan Sheet 2 of 2 Design View - 1]- If this work is to be done at locations 1, 2, 3 and 4 add them to the work description on the application. If not remove them from the Design View -1[Site Plan Sheet 2 of 2 Design View - 1]- Provide a TCP for the work described on the application: Overlash 121' starting at pole near 904 Shaw Rd continuing onto private property near 917 Shaw Rd [TCP Sheet 1 of 3]- Add work on E Pioneer to the job description or remove them from the Design View - 1 sheet [Application Sheet 2 of 2] | | | |

- TCP for splices 1-4 submitted
- Splice locations submitted with original application under work description: Maintenance
- Reference Sheet 4 of 5 in TCP for Overlash work