

City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Nov 19, 2024 Inspection Result: FAILED

Permit Number: B-20-0078

Property Address: 1515 S MERIDIAN, PUYALLUP, WA 98371;

Contractor: BALDWIN GENERAL CONTRACTING PO BOX 686, 0876 ALBANY, OR

93721

To construct: HAMPTON INN ADDITION & PARKING BELOW * REV (1) - 10/26/2023 -

LOCATION CHANGE FOR OIL/WATER SEPARATOR IN PARKING LOT * REV (2) - 12/27/2023 - UPDATES TO WALL TYPE, PLANS, SECTIONS, ELEVATIONS & SHEAR WALL DETAILS * REV (3) - 3/25/2024 - UPDATES

TO CHASE AND SHAFT WALLS

On this day we have inspected your construction for **Frame Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

- 1 1; complete framing as per engineering detail for framing at mechanical shafts at floor 2nd,3rd ,4th, as discussed with contractor.
 - not ready
- 2 NO ONE ON SITE AT TIME OF INSPECTION 11:15 AM
- 3 date of inspection 8/29/2024
 - 1.complete header framing per detail at stack 39 corridor on 2nd 3rd 4th floors
- 4 date of inspection 9/11/2024
 - 1.cancelled on site by contractor
- 5 Fire Sprinkler system is not active in the addition, this creates a fire risk that the contractor needs to address.
 - Contractor to immediately provide minimum of 2 layers of 5/8 type X fire rated GWB at all hallway connections.
 - These panels be removable but must be maintained closed and open only as needed for passage.



City of Puyallup

lay Cockerham

Building Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

Sincerely,

Ray Cockerham

Building Code Official RayC@PuyallupWA.gov

(253) 841-5585