

MERIDIAN FIRS LLC

TACOMA, WA 98411


PUYALLUP, WA 98371

LARRY DeCHANT

(253) 475-2405 DEARTH@DMCIMAIL.COM

PO BOX 456

C/O DMCI PO BOX 111088



PUYALLUP, WA 983742 (253) 314-9822 TOM@SOLUTIONS4STRUCTURES.COM

CASEY + DeCHANT ARCHITECTS, LLC

(253) 584-5207 CELL 253-677-0364

LDECHANT@CASEYDECHANTARCH.COM

SOLUTIONS 4 STRUCTURES, INC.

11605 135TH ST. CT. E.

Scope of Work

**Project Team** 

ARCHITECT:

**ENGINEER:** 

PROVIDE 42" HIGH PHYSICAL BARRIER AT SLIDING GLASS DOOR

TO PREVENT TENANT ACCESS TO EXTERIOR DURING

REMOVE CORNER OF EXISTING CONCRETE PATIOS AS NEEDED POUR NEW CONCRETE FOOTINGS PER DETAILS AT NEW POST


LOCATIONS WHERE CALLED OUT. ADD NEW BEAM & POSTS PER DETAILS WHERE CALLED OUT.

NO REPLACEMENT OF DOORS, WINDOWS, CONC. PATIOS, WALKS PROPOSED OR SCHEDULED.

NTERIOR WORK

1. NO INTERIOR WORK PROPOSED.

2923 S. MERIDIAN ST., PUYALLUP, WA



FOLLOW THE CONSTRUCTION DETAILS IN THE ATTACHED CONSTRUCTION DOCUMENT. HIDDEN OR UNKNOWN DEFECTS ARE NOT ADDRESSED IN THIS DOCUMENT.

CONTRACTOR IS RESPONSIBLE FOR DETERMINING QUANTITIES BY USING THE CONSTRUCTION DOCUMENTS, CONTRACTOR SITE OBSERVATIONS AND FIELD MEASUREMENTS.

PROVIDE DEMOLITION OF EXISTING MATERIALS AS REQUIRED TO COMPLETE THE SCOPE OF WORK AND AS OUTLINED IN THE CONSTRUCTION DOCUMENTS. LEGALLY DISPOSE OF ALL

INFORMATION SHOWN IN CONSTRUCTION DOCUMENTS IS SUBJECT TO THE REVIEW AND APPROVAL OF THE JURISDICTION AND MAY BE AMENDED THE CONTRACTOR SHALL DETERMINE THE EXACT LOCATION OF ALL EXISTING UTILITIES BEFORE COMMENCING WORK AND AGREES TO BE FULLY RESPONSIBLE FOR ANY AND ALL DAMAGES THAT INCUR DUE TO THE CONTRACTORS FAILURE

## **Owner/Contractor Coordination Notes**

TO LOCATE EXACTLY AND PRESERVE ANY AND ALL

UNDERGROUND UTILITIES.

THE FOLLOWING NOTES SHALL SERVE AS A GUIDE TO THE CONTRACTOR TO VERIFY E PROCEEDING WITH THEIR WORK. THE ITEMS OUTLINED BELOW ARE NOT INTENDED TO BE AN EXHAUSTIVE ANALYSIS OF A POSSIBLE AREAS OF CONCERN OR CONFLICT, BUT RATHER TO SERVE AS A BEGINNING

POINT IN IDENTIFYING COMMONLY OVERLOOKED AREAS IN THE CONSTRUCTION PROCESS REVIEW SPECIFICATION, MANUFACTURER'S PRODUCT LITERATURE, AND GENERAL NOTE

- SEALANT PRESSURE TREATED LUMBER METAL STRUCTURAL HANGERS, CLIPS, STRAPS, ETC. MEMBRANE FLASHING
  WEATHER RESISTANT BARRIER
- REVIEW LOCAL & STATE JURISDICTIONAL REQUIREMENTS FOR COMPLETE INSTALLATIONS OF THE FOLLOWING: A. CONCRETE FOOTINGS STRUCTURAL INSPECTIONS
- IF SPECIAL STRUCTURAL INSPECTIONS ARE REQUIRED BY IBC AND/OR THE CITY OF
- DRAWINGS PREPARED BY OTHERS ARE CONSIDERED ADDITIVE TO THE ARCHITECTUR DRAWINGS SUBMITTED

**Project Statistics** 

NUMBER OF DECKS: 6 DECKS

Vicinity Map

SITE ADDRESS:

City of Puyallup

**REVIEWED** 

COMPLIANCE

SKinnear

02/12/2025 3:00:50 PM CODE COMPLIANCE: 2021 INTERNATIONAL EXIST BLDG CODI

PUYALLUP, WA

0419032096

2923 S. MERIDIAN ST (BLDG J)

R-2 OCCUPANCY MULTI-FAMILY 2 STORY APARTMENTS



**Enlarged Site Map** EXISTING CONDITIONS AT DECKS: - DECKING REPLACEMENT COMPLETE - HORIZONTAL RAILING COMPLETE NEW PAINT COMPLETE 

**Photos of Existing Conditions** 

Casey + DeChant Architects, LLC Architecture And Planning

SEE ENLARGED SITE Approval of submitted plans is not an approval of omissions or oversights by this office or non compliance with any applicable regulations of local government. The contractor is responsible for making sure that the building complies with all applicable codes and regulations of the local government. The approved construction plans, documents, and all engineering must be posted on the job at all inspections in a visible and readily accessible location. Full sized legible color plans are Site Map required to be provided by the permitee on site for inspection. 31ST AVENUE SE

