

City of Puyallup Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection:	Apr 11, 2025	Inspection Result:	PARTIAL PASS
	PRDK20241969 2923 S MERIDIAN, PUYA	ALLUP, WA 98373;	
Contractor:			
To construct:	Replace(6) existing exterior deck boards with new decking and add		
	railing design boards to existing pickets. Provide new concrete footing,		
	p.t. post & p.t. beams under existing cantilevered deck framing for		
	additional support. ~ MERIDIAN FIRS DECKS REPLACEMENT - BLDG R		

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: Keep exposed spoils away from slopes. Remove all unused soil and concrete. Concrete washout in contained bins, not on the ground. All E&S inspections will be a partial pass until final.


Corrections:

Sincerely,

City of Puyallup



Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org



Jason Little Development Engineering Inspector JLittle@PuyallupWA.gov (253) 244-0387