



City of Puyallup

**Engineering Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

## INSPECTION REPORT

**Date of Inspection:** Aug 21, 2025

**Inspection Result:** **FAILED**

**Permit Number:** PRFUP20250721

**Property Address:** 115 2ND ST SE, PUYALLUP, WA 98372;

**Contractor:** PSE - INFRASOURCE 3130 S 38TH ST TACOMA, WA 98409

**To construct:** 108657975- WORK IN ROW TO RETIRE GAS SERVICE AT THE MAIN.  
ONE 4X3 ASPHALT CUT.

On this day we have inspected your construction for **Engineering Final Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** Please re-seal the corners. The overcuts re-appeared. Heat the existing AR so that it will run in the over cut. Let it settle then re-apply.

Note: Please DO NOT over cut patches when final paving.

Thank you.

**Corrections:**

Sincerely,

Jason Little



City of Puyallup

---

**Engineering Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

Development Engineering Inspector

[JLittle@PuyallupWA.gov](mailto:JLittle@PuyallupWA.gov)

(253) 244-0387