City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Feb 22, 2023 Inspection Result: PARTIAL PASS

Permit Number: E-21-0313

Property Address: 1015 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: DP EXCAVATION 11410 316th st e GRAHAM, WA 98338 (253) 720-

7790DP EXCAVATION 11410 316th st e GRAHAM, WA 98338 (253)

720-7790

To construct: PARKING LOT EXPANSION W. 675 STALLS, CFG~SHB-TC PARKING

EXPANSION/BENAROYA

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: Maintain TESC's and BMP's. As site contouring changes the TESC's will change w/ SWPPP updated.

See corrections.

Corrections:

- 1 Maintain CESCL inspections and SWPPP on site.
 - Remove a portion of the berm at the low point for the temp pond.
 - Zero track out. If need be, add spalls to help with tire cleaning. Keep asphalt clean.
 - May need to add a swale along the south side after cutting to grade.


Sincerely,



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org



Jason Little Engineering Tech IV JLittle@PuyallupWA.gov (253) 435-3636