



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

## INSPECTION REPORT

**Date of Inspection:** Mar 01, 2023                      **Inspection Result:**     **FAILED**

**Permit Number:** PRCTI20221551

**Property Address:** 3500 S MERIDIAN, Unit: 115, PUYALLUP, WA 98373;

**Contractor:** DOUBLE J ENTERPRISES LLC (DBA JEM CONSTRUCTION 29506 8TH AVENUE S ROY, WA 98580

**To construct:** Redemising and build-out of a part to the former Sears Building for a baseball training facility. NEW LEVEL 360Occupancy A-3 Approved reduced occupant load 388.

On this day we have inspected your construction for **Building Final Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:**

**Corrections:**

- 1 1 ; remove netting at all exit doors as discussed with Darren in old service center of sears.
- 2 ; remove thumb turns from exit door.
- 3 ; complete grout at exterior exit doors as per City approved plans.
- 4 ; complete door sweeps and threshold at not to exceed 1/2 at exterior doors.
- 5 ; complete accessible bathroom as per city approved plans. ( provide ADA compliant portable toilet with hand wash station until accessible restroom are completed & approved per city of Puyallup building inspector)
- 6 ; complete accessible restroom signage as per city approved plans.
- 7 ; patch holes in rated wall as discussed with Darren.
- 8 ; provide plumbing letter of capped plumbing to Building Official for approval.(covered with out inspection approval.)
- 9 ; complete rated walls and rated corridor as per city approved plans.
- 10 - complete seismic restrains at mechanical ducts as discussed with Darren.
- 11 ; complete posting of occupancy load signage as per city approved plans.
- 12 ; seal all penetration in vapor barrier at exterior walls.
- 13 ; complete framing & insulation at south and north exterior doors.
- 14 ; provide balance report with o.s.a. at time of inspection.



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

15 ; provide panic hardware at gate of electrical room as per city approved plans.

16 ; complete doors on netting as per a-700 of city approved plans.

17 - only half of training area for pitching approved for use until exit path and lighting completed as per City approved plans, & approved for use by City of Puyallup Building and Fire inspectors.

18 ; remove chain link fence at exterior exit of batting cage at s.w. corner as discussed with Darren.

19 ; remove existing restrooms as per demo sheets of city approved plans.(call for inspection of capped D.W.V. in slab prior to cover.)

Sincerely,

Shannon King  
Building Inspector 2  
[ShannonK@PuyallupWA.gov](mailto:ShannonK@PuyallupWA.gov)  
(253) 840-6684