



City of Puyallup

**Engineering Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

## INSPECTION REPORT

**Date of Inspection:** Mar 07, 2023                      **Inspection Result:**     **PARTIAL PASS**

**Permit Number:** E-21-0313

**Property Address:** 1015 39TH AVE SE, PUYALLUP, WA 98374;

**Contractor:** DP EXCAVATION 11410 316th st e GRAHAM, WA 98338 (253) 720-7790  
DP EXCAVATION 11410 316th st e GRAHAM, WA 98338 (253) 720-7790

**To construct:** PARKING LOT EXPANSION W. 675 STALLS,CFG~SHB-TC PARKING EXPANSION/BENAROYA

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** Dust on roadway has accumulated to 39th. Trucks are kicking up the dust as they enter and exit the site. Vehicles driving the same route are tracking through the seal coat parking lot. Today, the rain has come prior to sweeper arriving.

**Corrections:**

- 1 - Maintain CESCL inspections and SWPPP on site.
- Zero track out. Keep asphalt clean.
- Dust on roadway is trackout. Maintain sweeping/vac at least twice a day to minimize this.
- May need to add a swale along the south side after cutting to grade.

Sincerely,



City of Puyallup

---

**Engineering Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

A handwritten signature in black ink, consisting of a large, loopy initial 'J' followed by several vertical, wavy lines that resemble the letters 'LITTLE'. A horizontal line extends to the right from the end of the signature.

Jason Little  
Engineering Tech IV  
[JLittle@PuyallupWA.gov](mailto:JLittle@PuyallupWA.gov)  
(253) 435-3636