

City of Puyallup Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection:	Mar 23, 2023	Inspection Result:	FAILED
Permit Number: Property Address:	B-21-0518 401 15TH AVE SE, PUYAI	LUP, WA 98372;	
	HOWARD S WRIGHT 415 1ST AVE N SEATTLE, WA 98109 ADDITION OF (2) DELAYED EGRESS DOORS WITHIN THE EMERGENCY DEPT CORRIDORS ~MHS		

On this day we have inspected your construction for **Building Final Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

- 1 1; complete all requirements as noted on City approved plans at delayed egress doors prior to building final inspection. not ready
- 2 1 ; complete all requirements as noted on City approved plans at delayed egress doors prior to building final inspection. not ready
 2 : doors to remain open until working as per City approved plans and approved for use per

2 ; doors to remain open until working as per City approved plans and approved for use per building inspector.

Sincerely,

Shannon King Building Inspector 2 ShannonK@PuyallupWA.gov



City of Puyallup Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

(253) 840-6684