



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Apr 13, 2023

Inspection Result: **FAILED**

Permit Number: E-21-0313

Property Address: 1015 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: DP EXCAVATION 11410 316th st e GRAHAM, WA 98338 (253) 720-7790
DP EXCAVATION 11410 316th st e GRAHAM, WA 98338 (253) 720-7790

To construct: PARKING LOT EXPANSION W. 675 STALLS,CFG~SHB-TC PARKING EXPANSION/BENAROYA

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: dP somewhat cleaned up the low point where silt collects.

They are using an on site sweeper for the trucking today. I asked them for a street sweeper sooner than normal due to the amount of trucking.

2pm still no street sweeper! 3pm still no street sweeper!

Dirt has made its way onto 39th!

Corrections:

- 1 - Maintain CESCL inspections and SWPPP on site.
 - Zero track out. Keep asphalt clean.
 - Dust on roadway is trackout.

(Possible solutions: begin with sweeper on site ALL day, wash tires, turn spalls at end of each day, install construction road around entire site, etc..) These are suggestions to help mitigate track out. In no way is the city dictating means and methods.

- May need to add a swale along the south side after cutting to grade.
- Protect slopes.

Sincerely,



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

A handwritten signature in black ink, consisting of a large, loopy initial 'J' followed by a series of vertical, wavy lines that resemble a stylized 'L' or a series of connected loops. A horizontal line extends to the right from the middle of the signature.

Jason Little
Engineering Tech IV
JLittle@PuyallupWA.gov
(253) 435-3636