



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

**Date Issued** 07 Apr 2023  
**Permit Number** PRCA20220482  
**Contractor's Name** CROWN BUILDING

INSPECTIONS REQUIRED

**Planning Final Inspection** - Planning Final Inspection

**Fire Final Inspection** - Fire Final Inspection

**Engineering Final Inspection** - Engineering Final Inspection

**Wallboard / Drywall Inspection** - Wallboard / Drywall Inspection

**Underfloor Inspection** - Underfloor Inspection

**Shear Wall Inspection** - Shear Wall Inspection

**Re-Roof Inspection** - Re-Roof Inspection

**Hydrostatic Test 200Lbs 2Hrs** - Hydrostatic Test 200Lbs 2Hrs

**Frame Inspection** - Frame Inspection

**Foundation/Rebar Inspection** - Foundation/Rebar Inspection

**Footing/Setback Inspection** - Footing/Setback Inspection

**Firewall/Firestop Inspection** - Firewall/Firestop Inspection

**Fire Or Smoke Damper Inspection** - Fire Or Smoke Damper Inspection

**Exhaust/Vent Fans Inspection** - Exhaust/Vent Fans Inspection

**Erosion And Sediment Inspection** - Erosion And Sediment Inspection

**Building Final Inspection** - Building Final Inspection

**Block Wall Rebar Inspection** - Description



City of Puyallup

---

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

**Ceiling Grid/T-Bar Inspection** - Ceiling Grid/T-Bar Inspection

**Comment Building Div Inspection** - Comment Building Div Inspection

**Comment Engineering Div Inspection** - Comment Engineering Div Inspection

**Cover Inspection/Thrust Blocks Inspection** - Cover Inspection/Thrust Blocks Inspection

**Emergency Radio Test Review Inspection** - Emergency Radio Test Review Inspection

**Energy (Insulation) Inspection** - Energy (Insulation) Inspection

**Refrigeration Line Test Inspection** - Refrigeration Line Test Inspection

**Slab/Insulation Inspection** - Slab/Insulation Inspection

**Storm Inspection** - Storm Inspection