



City of Puyallup

**Engineering Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

## INSPECTION REPORT

**Date of Inspection:** Apr 18, 2023

**Inspection Result:** **FAILED**

**Permit Number:** E-21-0313

**Property Address:** 1015 39TH AVE SE, PUYALLUP, WA 98374;

**Contractor:** DP EXCAVATION 11410 316th st e GRAHAM, WA 98338 (253) 720-7790  
DP EXCAVATION 11410 316th st e GRAHAM, WA 98338 (253) 720-7790

**To construct:** PARKING LOT EXPANSION W. 675 STALLS,CFG~SHB-TC PARKING EXPANSION/BENAROYA

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** SEE CORRECTIONS!!!

**Corrections:**

- 1 - Maintain CESCL inspections and SWPPP on site.
  - Zero track out. ZERO TRAC OUT!!! KEEP THE SPALLS TURNED AND CLEANED!!! Keep asphalt clean.
  - Dust on roadway is trackout.  
(Possible solutions: begin with sweeper on site ALL day, wash tires, turn spalls at end of each day, install construction road around entire site, etc..) These are suggestions to help mitigate track out. In no way is the city dictating means and methods.
  - May need to add a swale along the south side after cutting to grade.
  - Protect slopes.

Sincerely,



City of Puyallup

---

**Engineering Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

A handwritten signature in black ink, consisting of a large, loopy initial 'J' followed by a series of vertical, wavy lines that resemble the letters 'LITTLE'. A horizontal line extends from the right side of the signature.

Jason Little  
Engineering Tech IV  
[JLittle@PuyallupWA.gov](mailto:JLittle@PuyallupWA.gov)  
(253) 435-3636