



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Jun 01, 2023

Inspection Result: NOT READY

Permit Number: PRRWF20230497

Property Address: 1015 39TH AVE SE, PUYALLUP, WA 98374;

Contractor:

To construct: Proposed retaining walls within Benaroya parking lot expansion project.

On this day we have inspected your construction for **Footing/Setback Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

- 2 1. provide step detail from engineer of record
2. complete all rebar per city approved plans
3. provide special inspections approval for bar placement, size, and spacing at time of next inspections
4. provide geo tech reports for soil barring
5. not ready

Sincerely,

Kevin Spruell
Building Inspector I
KSpruell@PuyallupWA.gov
(253) 841-5590