

City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Sep 14, 2023 Inspection Result: FAILED

Permit Number: PRCTI20221793

Property Address: 3500 S MERIDIAN, Unit: 930, PUYALLUP, WA 98373;

Contractor: WASHINGTON PATRIOT CONST LLC 10421 BURNHAM DR SUITE NW

GIG HARBOR, WA 98332

To construct: Construction of a swim school including the pool in the former Sears

store located in the South Hill Mall ~ GOLDFISH SWIM SCHOOL

On this day we have inspected your construction for **Mechanical Final Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

- 1 1; secure hot water tank prior to next inspection.
 - 2; complete install of self closer at acid room door.
 - 3; remove plastic bag from smoke detector in boiler room.
 - 4; provide all back flow certs. at time of next inspection.
 - 5; insulate all hot water supply lines in boiler room.
 - 6; complete all T.P.R. valve drains to mop sink.
 - 7; complete drain for back flow to mop sink.
 - 8; complete all permanent signage at exit doors, restrooms, changing rooms, occupant load signage as per City approved plans.
 - 9; complete shower trim at public showers.
 - 10; complete plumbing boots at sinks at restrooms.
 - 11; complete ceiling at electrical room.
 - 12; complete accessible benches in restroom as per City approved plans.
 - 13; complete urinal 17" max. a.f.f. in restroom as per City approved plans.
 - 14; complete vertical grab bars at mens & womens restroom 39"-41" as per City approved plans.
 - 15; complete door hardware at vestibule front door.
 - 16; complete stairs at pool as per Detail 6 of page AQ2.1



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

17; complete trap primers at shower as discussed with contractor.

18; complete handrail at stairs as per City approved plans.

19; remove all construction debris from accessible route, parking lot and containers as discussed with contractor.

20; remove all construction debris from roof.

21; paint all new gas pipe on roof and next to gas meter.

22 . need to review balance reports and final letters at next inspection. (not ready)

Sincerely,

Shannon King

Building Inspector 2

ShannonK@PuyallupWA.gov

(253) 840-6684