City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Permit Number: B-21-0712

Property Address: 1922 5TH AVE SW, PUYALLUP, WA 98371;

Contractor:

To construct: 2-STORY GARAGE BLDG/MECH/PLUMB

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: silt fence is missing the wire backing. Maintain the fence throughout the project.

Corrections:

Sincerely,

Jeff Hill Engineering Tech IV Jhill@PuyallupWA.gov (253) 841-5424