

City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Nov 03, 2023 **Inspection Result: NOT READY**

Permit Number: PRRWF20230497

Property Address: 1015 39TH AVE SE, PUYALLUP, WA 98374;

Contractor:

To construct: Proposed retaining walls within Benaroya parking lot expansion project.

* REVISION (1) - 9/1/2023 - WALL REVISIONS TO PROVIDE STRUCTURAL

COMPONENTS

On this day we have inspected your construction for **Footing/Setback Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

- 1 1. provide step detail from engineer of record
 - 2.complete all rebar per city approved plans
 - 3. provide special inspections approval for bar placement, size, and spacing at time of next inspections
 - 4. provide geo tech reports for soil barring5.not ready
- 2 1. complete items from previous inspection
- 3 1. provide city approved plans on site at time of next inspection 2.not ready

Sincerely,

Kevin Spruell Building Inspector I KSpruell@PuyallupWA.gov (253) 841-5590



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org