

## City of Puyallup

### **Building Division**

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

#### INSPECTION REPORT

**Date of Inspection:** Nov 07, 2023 **Inspection Result: NOT READY** 

Permit Number: PRRWF20230497

**Property Address:** 1015 39TH AVE SE, PUYALLUP, WA 98374;

Contractor:

**To construct:** Proposed retaining walls within Benaroya parking lot expansion project.

\* REVISION (1) - 9/1/2023 - WALL REVISIONS TO PROVIDE STRUCTURAL

**COMPONENTS** 

On this day we have inspected your construction for **Footing/Setback Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

#### Comments:

#### Corrections:

- 1 1. provide step detail from engineer of record
  - 2.complete all rebar per city approved plans
  - 3. provide special inspections approval for bar placement, size, and spacing at time of next inspections
  - 4. provide geo tech reports for soil barring
  - 5.not ready
- 2 1. complete items from previous inspection
- 3 1. provide city approved plans on site at time of next inspection 2.not ready
- 4 1. no one on site at time of inspection 11:40 AM

Sincerely,

Kevin Spruell Building Inspector I KSpruell@PuyallupWA.gov



# City of Puyallup

# Building Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

(253) 841-5590