

#### City of Puyallup

## **Building Division**

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

## INSPECTION REPORT

Date of Inspection: Nov 27, 2023 Inspection Result: NOT READY

**Permit Number:** PRRWF20230497

**Property Address:** 1015 39TH AVE SE, PUYALLUP, WA 98374;

Contractor:

**To construct:** Proposed retaining walls within Benaroya parking lot expansion project.

\* REVISION (1) - 9/1/2023 - WALL REVISIONS TO PROVIDE STRUCTURAL

COMPONENTS

On this day we have inspected your construction for **Footing/Setback Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

#### Comments:

#### Corrections:

- 1 1; provide geo-tech approval at time of inspection.
  - 2; complete all rebar as per city approved plans.
  - 3; provide min. clearances from soil to rebar and forms to rebar
  - $\mathbf{4}$ ; provide special inspection approval .

not ready

Sincerely,

Shannon King Building Inspector 2

Shannon K@Puyallup WA.gov



## City of Puyallup

# **Building Division**

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

(253) 840-6684