



City of Puyallup

**Engineering Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

## INSPECTION REPORT

**Date of Inspection:** Dec 05, 2023                      **Inspection Result:**      **PARTIAL PASS**

**Permit Number:** PRROW20231468

**Property Address:** 1201 39TH AVE SW, PUYALLUP, WA 98373;

**Contractor:** BRIGHTVIEW LANDSCAPING 5524 E. 66th AVENUE PUYALLUP, 98371

**To construct:** Closure of sidewalk to preform landscaping work on private property next to the sidewalk

On this day we have inspected your construction for **Comment Engineering Div Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** Landscape contractor finished up the stock pile for the day. They have a day or two left, not real sure if they will work during the heavy rain.

Note: The stock pile and lay down area is located in the SE corner near the 39th entrance.

**Corrections:**

- 1 - Install a catch basin insert near stock pile area.  
- Protect stock pile and CB from any silt runoff.

Sincerely,



City of Puyallup

**Engineering Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

Jason Little

Engineering Tech IV

[JLittle@PuyallupWA.gov](mailto:JLittle@PuyallupWA.gov)

(253) 435-3636