



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Dec 05, 2023 **Inspection Result:** **FAILED**

Permit Number: E-21-0313

Property Address: 1015 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: DP EXCAVATION 11410 316th st e GRAHAM, WA 98338 (253) 720-7790
DP EXCAVATION 11410 316th st e GRAHAM, WA 98338 (253) 720-7790

To construct: PARKING LOT EXPANSION W. 675 STALLS,CFG~SHB-TC PARKING EXPANSION/BENAROYA

On this day we have inspected your construction for **Engineering Daily Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: See E&S inspection report.

Concrete contractor is working curb forms. They tried pouring curbs today but the rain and mud was way to wet to finish.

dP imported sand for the PSE gas main. PSE worked on the bypass for the main relocate..

Note: The pond lost 2' of capacity since this morning. I am urging the contractor to install a plug with kickers on the inlet side of the flow control structure on site. This need to happen before direct discharge to the lake and/or ditch lines to wetlands in the area.

Corrections:

Sincerely,



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

A handwritten signature in black ink, consisting of a large, loopy initial 'J' followed by several vertical, wavy lines that resemble the letters 'LITTLE'. A horizontal line extends from the end of the signature to the right.

Jason Little

Engineering Tech IV

JLittle@PuyallupWA.gov

(253) 435-3636