

City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Dec 19, 2023 Inspection Result: NOT READY

Permit Number: PRCNC20221036

Property Address: 1601 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: ABSHER CONSTRUCTION CO. PO BOX 280 PUYALLUP, WA 98371-0152

To construct: New ~54,000 SF building containing labs, classrooms, faculty and

student spaces. REVISION (1) -003/21/2023 - ADDED DETAILS & DESIGN REFINEMENT FROM PERMIT SET TO IFC SET OF DOCUMENTS

(NO CHANGE IN SQ FTG OR COST)

On this day we have inspected your construction for **Frame Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

- 1 1; complete 4 stud pack at grid line (B1,A1-A4) as discussed with contractor.
 - 2; complete anchor bolt at plate break at grid line (B7,A!-A\$)
 - 3; (D6,C1-C7) roof framing of parapet complete.
- 2 1; inspection at 3rd floor head of wall insulation detail not complete at time of inspection
 - 2; 2 screws at 16" o.c. not complete at several locations of top track for top 6' for pre-rock. not ready

Sincerely,

Shannon King



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

Building Inspector 2 ShannonK@PuyallupWA.gov (253) 840-6684