



**DAILY FIELD REPORT**

**AAR TESTING AND INSPECTION, INC.**

7126 180th Ave NE, Suite C101  
Redmond, WA 98052  
425-881-5812

**Inspection Date**  
08/02/2023

**Report Number**  
LDC080223A

| CLIENT INFORMATION |                   | PROJECT INFORMATION |                             |
|--------------------|-------------------|---------------------|-----------------------------|
| <b>Contact</b>     | Kevin Simoskevitz | <b>Project No.</b>  | 23-474                      |
| <b>Company</b>     | Raymond West      | <b>Project Name</b> | Red Dot Corp (PO20069121-E) |
| <b>Address</b>     | 6607 S 287th St   | <b>Address</b>      | 2504 E Main Ave             |
| <b>City</b>        | Auburn            | <b>City</b>         | Puyallup                    |
| <b>Contractor</b>  | Raymond West      | <b>Permit No.</b>   | PRCTO20230997               |

| INSPECTION TYPE(S)   | STRUCTURE(S) / LOCATION(S)            |
|--|---------------------------------------|
| <input checked="" type="checkbox"/> <b>Proprietary Anchors - Epoxy Anchors</b> | Kardex units 1 and 2 at fastenal cage |

| Weather | Temperature (°F) | Start Time | End Time |
|---------|------------------|------------|----------|
| Sunny   | 81               | 12:00 PM   |          |

| DRAWINGS / DOCUMENTS REFERENCED |
|---------------------------------|
| Structural calculations         |

| INSPECTION OBSERVATION / REMARKS  |
|---|
| Verified epoxy to be Hilti RE 500 V3, exp: 03/2024. Verified hole cleanliness and minimum embedment of 4.5". Observed placement of epoxy and 5/8" Hilti HAS-B 105 all threads forming a fully encapsulated system. 40 anchors placed at baseplate perimeter of each unit. |

**Items inspected are in conformance with approved plans, specifications, and jurisdictional requirements**

**Inspectors Signature**

**Inspectors Name**  
Loren Chandler

**Report Date**  
08/02/2023

**Reviewers Signature**

**Reviewed By**  
Tejalam (TJ) Gounden

**Reviewed Date**  
08/05/2023




**DAILY FIELD REPORT**  
**AAR TESTING AND INSPECTION, INC.**  
7126 180th Ave NE, Suite C101  
Redmond, WA 98052  
425-881-5812

**Inspection Date**  
08/02/2023

**Report Number**  
LDC080223A

**PHOTOS**



**Inspectors Signature**

**Inspectors Name**  
Loren Chandler

**Report Date**  
08/02/2023

**Reviewers Signature**

**Reviewed By**  
Teajalam (TJ) Gouden

**Reviewed Date**  
08/05/2023

AE29649B-5BBE-4FBE-B3C3-FFEE12DB64E