



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Feb 20, 2024

Inspection Result: **FAILED**

Permit Number: PRRASF20221703

Property Address: 1404 SHAW RD, PUYALLUP, WA 98372;

Contractor: MICHAEL E ALLEN CONST INC 3623 32ND AVE E TACOMA, WA 98443-1600

To construct: Building an addition of 2,905 square feet with a 2 car garage of 732 square feet.

On this day we have inspected your construction for **Combination Frame And Rough In Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

- 1 1 ;provide attic access in garage.
- 2 ; complete blocking of trusses at 1st and 2nd floor as discussed with contractor.
- 3 ; no back to back electrical boxes in garage firewall.
- 4 ; strap top plate break at beam to wall at rear of house in kitchen.
- 5 ; complete draftstop at top and bottom plates to complete firestop at electrical and d.w.v. penetrations.
- 6 ; complete hangers at stairs as discussed with contractor.
- 7 ; seal top of chases to complete firestop.
- 8 ; provide full bearing at 6"x6" post in living room.
- 9 ; strap top plate break at addition to existing house at front of house.
- 10 ; complete deck ledger as per detail #9 of city approved plans.
- 11 ; provide engineering floor ledger attachment at front of house and complete attachment prior to next inspection.
- 12 ; complete D.F. #1 posts as per plans.
- 13 ; provide engineering for truss repair at 2nd floor at front of house.
- 14 ; complete upper roof venting above stairs.
- 15 . strap top plate break to beam above stairs.



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

16 ; gas pipe test approved at 15 psi.

17 ; approved test on d.w.v. and supply.

Sincerely,

Shannon King

Building Inspector 2

ShannonK@PuyallupWA.gov

(253) 840-6684