



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Feb 27, 2024 **Inspection Result:** **FAILED**

Permit Number: PRFO20240140

Property Address: 1023 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: HOWARD S. WRIGHT CONSTRUCTION CO. 415 1ST AVE #400 N
SEATTLE, WA 98109

To construct: Install concrete slab on grade pads and foundations for exterior
mechanical equipment, totaling 2,226 s.f. of concrete slab. CHILLER AND
COOLER FOUNDATIONS

On this day we have inspected your construction for **Foundation/Rebar Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

- 1 1 ; provide geo-tech approval for soil bearing of 3,000 psf as required per city approved plans.
- 2 2 ; provide min. 3" from soil to rebar and min. clearance from forms to rebar.

Sincerely,

Shannon King

Building Inspector 2

ShannonK@PuyallupWA.gov

(253) 840-6684



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org