



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

## INSPECTION REPORT

**Date of Inspection:** Mar 13, 2024

**Inspection Result:** **FAILED**

**Permit Number:** PRDE20240287

**Property Address:** 2317 SHAW RD, PUYALLUP, WA 98374;

**Contractor:**

**To construct:** DEMO BARN & SHED ON PROPERTY

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** No erosion control installed.  
No construction entrance.

**Corrections:**

- 1 1. Install silt fence around the work area.
2. Install a construction entrance

Sincerely,

Jeff Hill  
Engineering Tech IV  
[Jhill@PuyallupWA.gov](mailto:Jhill@PuyallupWA.gov)  
(253) 841-5424