



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Apr 04, 2024

Inspection Result: NOT READY

Permit Number: PRCTI20240333

Property Address: 1023 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: HOWARD S WRIGHT 415 1ST AVE N SEATTLE, WA 98109

To construct: Interior tenant improvements to construct new UPS ROOM of 2,223 s.f.
and new BATTERY ROOM of 1,474 s.f. - CENTERIS VOLTAGE PARK

On this day we have inspected your construction for **Frame Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

- 1 1 ; inspection of battery room only.
2 ; provide special inspection approval of welding prior to next inspection.
3 ; provide engineers fix or approval of titen hd anchor installed at angle.
4 ; complete all framing and hardware install as per city approved plans as discussed with contractor.
not ready
- 2 1 ; provide engineers fix or approval for welding performed without periodic special inspection.
2 ; complete titen hd anchors at 3 locations as discussed with contractor at battery room.

Sincerely,

Kevin Spruell
Building Inspector I
KSpruell@PuyallupWA.gov
(253) 841-5590