



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Apr 08, 2024

Inspection Result: **FAILED**

Permit Number: E-21-0313

Property Address: 1015 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: DP EXCAVATION 11410 316th st e GRAHAM, WA 98338 (253) 720-7790
DP EXCAVATION 11410 316th st e GRAHAM, WA 98338 (253) 720-7790

To construct: PARKING LOT EXPANSION W. 675 STALLS,CFG~SHB-TC PARKING
EXPANSION/BENAROYA

On this day we have inspected your construction for **Engineering Daily Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: Last Friday visit there was no track out.

Arrived on site today and there have been trucks exiting from the parking lot with a ton or dirt and silt from the tires.

Aske TI GC and they have not accessed with concrete trucks. The TI GC said that dP exported ditch spoils.

dP states that they exported last Thursday. This is not true due to my site visit Friday.

Note: Someone IS NOT telling the truth.

After walking the site, there appears to be no concrete truck access from below!

Corrections:

- 1 - Install correct bolts. The size is correct but they need to be stainless steel with Teflon coated nuts.
 - The meter leaks at one of the gasket points.
 - The box is cracked and needs to be replaced.
 - The 4 blocks need to be placed along the long side not to exceed the inside edge.
 - The bypass needs to be cleaned out and a cover installed.

Sincerely,



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

Jason Little
Engineering Tech IV
JLittle@PuyallupWA.gov
(253) 435-3636