



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: May 29, 2024 **Inspection Result:** **PARTIAL PASS**

Permit Number: PRCTI20240438

Property Address: 1023 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: HOWARD S. WRIGHT CONSTRUCTION CO. 415 1ST AVE #400 N
SEATTLE, WA 98109

To construct: Installation of exterior wall penetration assemblies and supplementary
metal stud framing and steel headers. BLDG ONLY

On this day we have inspected your construction for **Energy (Insulation) Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: inspection of framing complete at wall cavity of Generator yard conduit prior to spray foam insulation.

Corrections:

Sincerely,

Shannon King
Building Inspector 2
ShannonK@PuyallupWA.gov
(253) 840-6684