



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Jun 11, 2024

Inspection Result: PASSED

Permit Number: PRCNC20240647

Property Address: 1023 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: HOWARD S WRIGHT 415 1ST AVE N SEATTLE, WA 98109

To construct: Construct 1,144 sf metal building housing electrical switchgear - CENTERIS VOLTAGE PARK - REV (1) - 6/3/2024 - RECLASSIFY THE METAL BUILDING TO "LOW ENERGY BUILDING" - DELETE ALL INSULATION MATERIAL IN THE EXTERIOR ENVELOPE INCLUDING ROOF, WALL AND SLAB EDGE ASSEMBLIES

On this day we have inspected your construction for **Shear Wall Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: CUSTOMER REQUESTING 6AM INSPECTION, MADE ARRANGEMENTS PER SK/KS -JF

Corrections:

Sincerely,

Shannon King
Building Inspector 2
ShannonK@PuyallupWA.gov
(253) 840-6684