



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Jul 09, 2024

Inspection Result: **FAILED**

Permit Number: PRCCP20231400

Property Address: 1601 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: LINCOLN CONSTRUCTION INC 11803 101st Ave Ct E, Suite 201
Puyallup, WA 98373 (253) 847-6414

To construct: PARKING LOT A; PARKING IMPROVEMENTS: ASPHALT
PAVING; CONCRETE PAVING & STORMWATER ~ PIERCE COLLEGE
PARKING EXPANSION

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: Silt fence is partially up, No tree protection fencing, no dust control.
See corrections.

Corrections:

- 1 - Dust control needs to be provided prior to any more work!
 - Finish silt fence where needed. If fill is going to be higher than surrounding areas, silt fence needs to be installed.
 - Install tree protection fence where needed.

Sincerely,



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

A handwritten signature in black ink, consisting of a large, loopy initial 'J' followed by a series of vertical, wavy lines that resemble the letters 'LITTLE'. A horizontal line extends from the end of the signature to the right.

Jason Little

Development Engineering Inspector

JLittle@PuyallupWA.gov

(253) 435-3636