



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Jul 10, 2024

Inspection Result: **PARTIAL PASS**

Permit Number: PRCCP20231400

Property Address: 1601 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: LINCOLN CONSTRUCTION INC 11803 101st Ave Ct E, Suite 201
Puyallup, WA 98373 (253) 847-6414

To construct: PARKING LOT A; PARKING IMPROVEMENTS: ASPHALT
PAVING; CONCRETE PAVING & STORMWATER ~ PIERCE COLLEGE
PARKING EXPANSION

On this day we have inspected your construction for **Erosion And Sediment Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: Contractor supplied material for dust control.

Most of the fencing is up and should be finished when wood chipping has been completed.

Corrections:

- 1 - Maintain dust control!
 - Finish silt fence where needed. If fill is going to be higher than surrounding areas, silt fence needs to be installed.
 - Finish tree protection where and if needed.
 - Keep road clean as needed.

Sincerely,



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

Jason Little

Development Engineering Inspector

JLittle@PuyallupWA.gov

(253) 435-3636