

City of Puyallup **Engineering Division** 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection:	Jul 12, 2024	Inspection Result:	PARTIAL PASS
Permit Number:	PRFUP20231536		
Property Address:	1006 39TH AVE SE, PUYALLUP, WA 98374;		
Contractor:	PSE - INFRASOURCE 31	30 S 38TH ST TACOMA	, WA 98409
To construct:	PERMIT EXT TO 12/29/2	024 109145875 - Gas M	Vain remediation - Install
	1598' of 2" gas main, we will replace 8 services and install 7 test sites		
	(T&T). Sidewalk was considered but not enough room for our gas utilities to be safely installed requesting hard surface cuts - detailed in restoration plan. Work is primarily on 10th St SE.		

On this day we have inspected your construction for **Close All Restoration Complete Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: All asphalt patching on 10th has been completed. See corrections below.

Corrections:

- 1 Schedule 48hrs prior to concrete restoration.
 - Please bring jumpin jack for deep compaction during concrete restoration.
 - Schedule dental parking lot asphalt restoration 48hrs prior to work.
 - Schedule 48hrs prior to work for intersection of 39th and 10th asphalt patch and G&O.


- Intersection of 39th and 10th will need to be two separate nights. 1st night will be patch AND replacement of MH frame and cover (supplied by city) and GV housing set to grade with thickened asphalt and pave around monument. 2nd night will be G&O. Note: Please have white temp tape on site!

Sincerely,

City of Puyallup



Engineering Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org



Jason Little Development Engineering Inspector JLittle@PuyallupWA.gov (253) 435-3636